

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 23 S., R. 7 W.

CHAINS

Land, rolling south of Umpqua River and mountainous to the north.

Soil, sandy clay loam.

Timber, fir, hemlock, cedar, alder, maple, willow, ash, chinquapin, and madrone; undergrowth, vine maple, hazel, arrowwood, blackberry, Scotch broom, huckleberry, salmonberry, salal, poison oak, and fern.

## Meanders of the Umpqua River

From the meander cor. of secs. 21 and 22, heretofore described; thence downstream with the adjusted meanders of the left bank of the river through sec. 21, along a precipitous NE. slope.

N. 15° 05' W., 27.05 chs. Descend 187 ft. on this course.

N. 2° 02' E., 12.16 chs. Descend 281 ft. on this course. At end of course the meander cor. of secs. 16 and 21, monumented with an iron post, 2½ ins. diam., firmly set, projecting 6 ins. above ground, marked and witnessed as described in the official record.

## Subdivision of Sec. 21, T. 23 S., R. 7 W.

The following subdivision of section was executed in conformity with legal surveying practice. The record of true line notes only is set forth in the following field notes.

From the ¼ sec. cor. of secs. 21 and 28.

N. 0° 57' W., along the N. and S. center line of sec. 21.

Descend 17 ft. along W. slope, through scattering timber and dense undergrowth.

- 2.10 Ravine, drains S. 40° W.; asc. 295 ft. over SW. slope.
- 8.80 Spur, slopes N. 60° W.; desc. 62 ft. over N. slope.
- 11.15 Ravine, drains N. 70° W.; asc. 79 ft. over S. slope.
- 12.80 Top of ascent, slopes W.; desc. 63 ft. along broken W. slope.
- 27.90 Ravine, drains S. 40° W.; enter open pasture land, edge bears E. and W.; asc. 91 ft. over SW. slope.
- 36.50 Enter scattering timber and dense undergrowth, edge bears E. and W.
- 40.22 Point for the center ¼ sec. cor. of sec. 21, at intersection with the E. and W. center line.
- Set an iron post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap marked

C¼ S 21

1963