

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 30 S., R. 9 W.

CHAINS

A cedar, 22 ins. diam., bears S. 35 3/4° E., 69 lks, dist., with scribe marks T30S R9 visible on partly healed blaze.

A fir, 18 ins. diam., bears S. 50° W., 46 1/2 lks. dist., with a healed blaze.

A fir, 70 ins. diam., bears N. 36 1/2° W., 31 lks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, and in a mound of stone, 2 ft. base, to top, with brass cap marked

T	30	S	R	9	W
	S	5	S	4	
	S	8	S	9	
					1962

*FD. ok
1/18 R. Sturtevant
11-20-20*

from which a new bearing tree,

A cedar, 35 ins. diam., bears N. 12 1/2° E., 36 lks. dist., marked T30S R9W S4 BT.

Deposit basalt stone alongside the iron post.

N. 89° 12' W., bet. secs. 5 and 8.

Descend 55 ft. over SW. slope, through heavy timber and dense undergrowth.

2.55 Ravine, drains S. 10° W.; asc. 95 lks. over SE. slope.

10.00 Edge of logged area, bears N. and W., with heavy old growth timber to the S.

11.15 Ridge, bears NE. and SW.; desc. 300 ft. over NW. slope.

39.00 Creek, 2 lks, wide, course SW.; asc. 5 ft. over SE. slope.

40.09 The 1/4 sec. cor. of secs. 5 and 8, determined at record bearing and distance from a line tree marked by William M. Bushey, in 1893:

A fir, 65 ins. diam. bears West, 17 lks. dist., with 2 notches each on E. and W. sides.

The corner has been obliterated by logging operations; the only other remaining evidence is the yew bearing tree in Sec. 8, 14 ins. diam., fallen and dozed out of position, with axe marks indicating the old blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 21 ins. in the ground, with brass cap marked

	1/4	S	5		
		S	8		
T	30	S	R	9	W
					1962

*FD. ok
1/18 R. Sturtevant
11-20-20*

from which new bearing trees:

A fir, 6 ins. diam., bears N. 3 1/2° W., 20 1/2 lks. dist., marked 1/4 S5 BT.