

County Surveyor's Record, Douglas County, Oregon

7

Dependent Resurvey, Subdivisional Lines, T. 30 S., R. 9 W.

CHAINS

A fir, 19 ins. diam., bears N. 29° E., 93 lks. dist., marked $\frac{1}{4}$ S5 BT.

A hemlock, 10 ins. diam., bears S. $23\text{-}3/4^{\circ}$ W., 45 lks. dist., marked $\frac{1}{4}$ S6 BT.

An iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., set 25 ins. in the ground, for a reference monument, bears S. 45° W., 50 lks. dist., with brass cap marked RM S6 1962 and an arrow pointing to the corner.

N. 0° $30'$ W., beginning new measurement.

Ascend 220 ft. over S. slope.

- 5.78 Base of rock bluff, 60 ft. high faces SW.; asc. 60 ft. over bluff.
- 6.54 Point of spur, slopes W.; desc. 20 ft. over NW. slope.
- 7.60 Ravine, drains S. 55° W.; asc. 60 ft. over SE. slope.
- 10.05 Spur, slopes S. 60° W.; desc. 124 ft. over NW. slope.
- 19.30 Creek, 8 lks. wide, course S. 80° W.; asc. 26 ft. over SE. slope.
- 27.50 Creek, 6 lks. wide, course S. 15° E.; asc. 286 ft. over precipitous S. slope.
- 36.65 Base of rock bluff, 60 ft. high, faces S.; asc. 90 ft. over bluff and steep S. slope.
- 37.48 The cor. of secs. 5, 6, 31, and 32, on the N. bdy. of the Tp., monumented with the basalt stone, 16 x 12 x 8 ins., firmly set 12 ins. in the ground by William Porter, in 1907, marked with 5 notches on the E., and 1 on the W. edge, from which the 1893 bearing trees:

A fir snag, 40 ins. diam., bears N. 80° E., 102 lks. dist., with scribe mark B visible on burned blaze.

A rotted fir snag, 43 ins. diam., bears S. $34\text{ }3/4^{\circ}$ E., $49\frac{1}{2}$ lks. dist., with no marks remaining. (Record bearing and distance, S. $29\text{-}3/4^{\circ}$ E., $54\frac{1}{2}$ lks.)

A fir, 47 ins. diam., bears S. 60° W., 76 lks. dist., with scribe marks T3 R9 S6 visible on burned blaze. (Record distance, 79 lks.)

A fir snag, 45 ins. diam., bears N. $38\frac{1}{2}^{\circ}$ W., 42 lks. dist., with no marks remaining.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap marked

T 29 S R 9 W
S 31 S 32
S 6 S 5
T 30 S
1962

from which new bearing trees: