

County Surveyor's Record, Douglas County, Oregon

9

Dependent Resurvey, Portion of W. Bdy. T. 31 S., R. 8 W.

CHAINS

$$\begin{array}{c} \frac{1}{4} \\ S\ 1\ | S\ 6 \\ R\ 9\ W\ | R\ 8\ W \\ T\ 31\ S \\ 1962 \end{array}$$

from which new bearing trees

A fir, 20 ins. diam., bears N. $67\frac{1}{2}^{\circ}$ E., 24 lks.
dist., mkd. $\frac{1}{4}$ S6 BT.

A fir, 13 ins. diam., bears N. $74\frac{1}{2}^{\circ}$ W., 41 lks.
dist., mkd. $\frac{1}{4}$ S1 BT.

N. 0° 08' E., beginning new measurement.

Descend 415 ft. over broken NE. slope, through heavy
timber and moderate undergrowth.

24.00 Ravine, drains N. 80° E.; asc. 110 ft. over SE. slope.

29.00 Spur, slopes N. 70° E.; desc. 50 ft. over NW. slope,
changing to N. slope.

30.87 The cor. of Tps. 30 and 31 S., Rs. 8 and 9 W.,
determined from the remains of the original bearing
trees:

A down fir, 27 ins. diam., bears N. 2° E., 36
lks. dist., 43 lks. slope distance, mkd. with
a healed blaze. (Record distance, 43 lks.)

A fir, 51 ins. diam., bears S. 38° E., 59 lks.
dist., to the face, mkd. with old axe marks and
rotting bark blaze. (Record, S. 40° E., 57 lks.)

A fir, 35 ins. diam., bears S. 68° W., 38 lks..
dist., mkd. with a healed blaze. (Record
bearing, S. 75° W.) Remarkd T31S R9W S1BT.

A fir, 27 ins. diam., bears N. $72\frac{1}{2}^{\circ}$ W., 25 lks.
dist., mkd. with a healed blaze. (Record
bearing, N. 63° W.) Remarkd T30S R9W S36 BT.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins.
in the ground, with brass cap mkd.

$$\begin{array}{c} T\ 30\ S \\ R\ 9\ W\ | R\ 8\ W \\ S\ 36\ | S\ 31 \\ \hline S\ 1\ | S\ 6 \\ T\ 31\ S \\ 1962 \end{array}$$

from which

A fir, 35 ins. diam., bears N. $54\frac{1}{4}^{\circ}$ E., 53 lks.
dist., mkd. T30S R8W S31 BT.

A fir, 15 ins. diam., bears S. $22\frac{1}{2}^{\circ}$ E., 25 lks.
dist., mkd. T31S R8W S6 BT.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, oak, madrone, chinquapin, cedar,