

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 31 S., R. 8 W.

CHAINS

from which

A white fir, 8 ins. diam., bears S. $17\frac{1}{2}^{\circ}$ E., 23 lks. dist., mkd. $\frac{1}{4}$ S11 BT.

A fir, 6 ins. diam., bears N. 87° W., 31 lks. dist., mkd. $\frac{1}{4}$ S10 BT.

Descent 160 ft. over NE. slope.

45.05 Ravine, drains E.; dirt road, 25 lks. wide, bears N. 20° E., and S. 30° W.; asc. 40 ft. over SE. slope.

48.85 Spur, slopes N. 60° E., desc. 220 ft. over broken NE. slope.

50.20 Dirt road, 25 lks. wide, bears N. 30° W. and S. 30° E.

59.25 Creek, 3 lks. wide, course NE.; desc. 200 ft. over broken NE. slope.

74.50 Creek, 5 lks. wide, course NE.; asc. 55 ft. over SE. slope.

76.85 Spur, slopes N. 75° E.; desc. 70 ft. over NE. slope.

80.42 The cor. of secs. 2, 3, 10, and 11, determined at record bearing and distance from the original SE. bearing tree:

A cedar, 20 ins. diam., bears S. 66° E., 46 lks. dist., with an opened blaze and cruiser mark, "I".

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd.

T 31 S R 8 W
 S 3 S 2
 S 10 S 11
 1961

from which new bearing trees

A fir, 8 ins. diam., bears N. $13\frac{1}{2}^{\circ}$ E., 278 lks. dist., mkd. T31S R8W S2 BT.

A hemlock, 6 ins. diam., bears S. 56° E., 45 lks. dist., mkd. T31S R8W S11 BT.

A hemlock, 18 ins. diam., bears S. 85° W., 124 lks. dist., mkd. T31S R8W S10 BT.

A hemlock, 12 ins. diam., bears N. 26° W., 214 lks. dist., mkd. T31S R8W S3BT.

The sec. cor. is located at NW. corner of timber; edges of logged area bear E. and S.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, madrone, chinquapin, white fir, alder, and pine; undergrowth, young timber, salal, Oregon grape, vine maple, rhododendron, huckleberry, Hazel, live oak, poison oak, black raspberry, manzanita,