

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 31 S., R. 8 W.

CHAINS

$\frac{1}{4}$   
 S 16 | S 15  
 T 31 S | R 8 W  
 1961

from which

A fir, 35 ins. diam., bears N. 14° E., 45 lks. dist., mkd.  $\frac{1}{4}$  S 15 BT.

A fir, 14 ins. diam., bears N. 55° W., 42 lks. dist., mkd.  $\frac{1}{4}$  S 16 BT.

Descend 355 ft. over broken NE. slope.

49.85 Creek, 5 lks. wide, course N. 70° E.; asc. 350 ft. over broken SW. slope.

73.75 Dry creek, 3 lks. wide, course S. 45° E.; asc. 270 ft. over Sw. slope, changing to S. slope.

80.44 The cor. of secs. 9, 10, 15, and 16, determined at record bearing and distance from the remaining original bearing tree:

A fir, 32 ins. diam., bears N. 80° W., 26 lks. dist., mkd. T31S R8W S9 BT on bark blaze. Remarked T31S R8W S9 BT.

At the corner point

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T 31 S R 8 W  
 S 9 | S 10  
 S 16 | S 15  
 1961

FD OK BY TROY RAMBO  
6/2005 M148-7

from which new bearing trees

A fir, 25 ins. diam., bears N. 13° E., 55 lks. dist., mkd. T31S R8W S10 BT.

A fir, 13 ins. diam., bears S. 86° E., 80 lks. dist., mkd. T31S R8W S15 BT.

A fir, 23 ins. diam., bears S. 8° W., 37 lks. dist., mkd. T31S R8W S16 BT.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, pine, yew, live oak, madrone, maple, chinquapin; undergrowth, live oak, hazel, salal, huckleberry, poison oak, vine maple, ferns and vines.

From the cor. of secs. 10, 11, 14 and 15.

S. 89° 37' W., bet. secs. 10 and 15.

Descend 5 ft. over NW. slope, through heavy timber and moderate undergrowth.

2.40 Draw, drains N.; asc. 20 ft. over NE. slope.

4.35 Spur, slopes N. 20° E.; desc. 140 ft. over broken NW. slope.