

County Surveyor's Record, Douglas County, Oregon
-12-

Remonumentation of Certain Original Corner Points, T. 25 S., R. 2 W.

CHAINS

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 25 ins. in the ground, with brass cap marked
$$\frac{1}{4} \begin{array}{l} S 22 \\ S 27 \end{array}$$

T 25 S R 2 W
1962

from which a new bearing tree

A hemlock, 10 ins. diam., bears N. $58\frac{1}{2}^{\circ}$ E., 41 lks. dist., marked $\frac{1}{4}$ S22 BT.

Deposit the original corner stone alongside the iron post.

The $\frac{1}{4}$ Sec. cor. of secs. 21 and 22, perpetuated and recorded by V. W. Hosford in 1957, monumented with an iron pipe, 36 ins. long, $1\frac{1}{2}$ ins. diam., firmly set 22 ins. in the ground, at record bearing and distance from the faces of the original bearing trees:

A rotted pine snag, 40 ins. diam., bears S. 56° E., 22 lks. dist., with no marks remaining. (Record distance, 21 lks.)A cedar, 60 ins. diam., bears S. 80° W., 161 lks. dist., with no marks remaining on burned and rotted blaze. (Record distance, 157 lks.)

and bearing trees marked by Hosford in 1957

A fir, 17 ins. diam., bears N. 88° E., $7\frac{1}{2}$ lks. dist., with scribe marks 425 S BT visible on partly healed blaze. (waist high)A fir, 14 ins. diam., bears N. 23° W., $31\frac{1}{2}$ lks. dist., with scribe marks 425 BT visible on partly healed blaze. (Waist high)

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap marked
$$\frac{1}{4} \begin{array}{l} S 21 | S 22 \\ T 25 S R 2 W \\ 1962 \end{array}$$

Add the marks BT to base of bearing trees marked by Hosford.

Deposit iron pipe alongside and break clear glass bottle at base of the iron post.

The cor. of secs. 15, 16, 21 and 22, perpetuated and recorded by V. W. Hosford in 1957, monumented with an iron pipe, 36 ins. long, $1\frac{1}{2}$ ins. diam., firmly set 20 ins. in the ground, from which the original bearing trees;

A down hemlock, 6 ins. diam., bears N. 52° E., 38 lks. dist., with scribe marks S 2 S1 visible on unhealed blaze.A broken hemlock, 24 ins. diam., bears S. 45° E., 26 lks. dist., with fragmentary scribe marks visible on partly healed blaze.