

County Surveyor's Record, Douglas County, Oregon
-18-

Remonumentation of Certain Original Corner Points, T. 25 S., R. 2 W.

CHAINS

and trees marked by H. Boyer, County Surveyor, in 1943.

A down and rotted fir, 30 ins. diam., bears N. 87° E.,
30 lks. dist., with no marks remaining.

A maple, 14 ins. diam., bears S. 14½° E., 52½ lks. dist.,
with scribe marks ¼ S 8 BT visible on partly healed
double blaze.

and a tree marked by V. W. Hosford, in 1957

A down hemlock, 11 ins. diam., bears N. 61° W., 32 lks.
dist., with scribe marks ¼ S21 253 BT visible on
unhealed blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground,
with brass cap marked

$$\begin{array}{c} \frac{1}{4} \frac{S \ 21}{S \ 28} \\ T \ 25 \ S \ R \ 2 \ W \\ 1962 \end{array}$$

from which a new bearing tree

A hemlock, 6 ins. diam., bears N. 50° W., 12 lks. dist.,
marked ¼ S21 BT.

Deposit the original corner stone and reset the iron pipe
alongside the iron post

The ¼ sec. cor. of secs. 20 and 21, determined at record bearing
and distance from the original bearing trees:

A sawed fir stump, 38 ins. diam., bears N. 89° E.,
13 lks. dist., with fragmentary scribe marks visible
on opened blaze.

A down fir, 15 ins. diam., bears S. 35° W., 46 lks. dist.,
with no marks remaining.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground,
with brass cap marked

$$\begin{array}{c} \frac{1}{4} \\ S \ 20 \ | \ S \ 21 \\ T \ 25 \ S \ R \ 2 \ W \\ 1962 \end{array}$$

from which new bearing trees

A fir, 4 ins. diam., bears N. 79¼° E., 38 lks. dist.,
marked ¼ S21 BT.

A fir, 48 ins. diam., bears N. 64° W., 54 lks. dist.,
Marked ¼ S20 BT, and a nail, with a "W" embossed on
the head, at the base.

A steel tube, ½ ins. diam., protruding 12 ins. above
the ground, bears West, 2 lks. dist..