

County Surveyor's Record, Douglas County, Oregon

-28-

Remonumentation of Certain Original Corner Points, T. 25 S., R. 2 W.

CHAINS

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap marked
$$\frac{1}{4} \frac{S 7}{S 18}$$

T 25 S R 2 W
1962

from which a new bearing tree

A hemlock, 15 ins. diam., bears N. 50° W., 78 lks. dist.,
Marked $\frac{1}{4}$ S7 BT.

Deposit the original corner stone alongside the iron post.

The $\frac{1}{4}$ sec. cor. of secs. 7 and 8, monumented with a basalt stone, 17 x 12 x 8 ins., on surface of ground, marked $\frac{1}{4}$ on the W. face, & perpetuated and recorded by V. W. Hosford, 1957, by setting an iron pipe, 36 ins. long, $1\frac{1}{2}$ ins. diam., 24 ins. in the ground, alongside the original corner stone, from which the only remaining original bearing tree:

A down yew, 11 ins. diam., bears N. 33° W., 15 lks. dist.,
with fragmentary scribe marks visible on partly healed blaze.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap marked
$$\begin{array}{c} \frac{1}{4} \\ S 7 | S 8 \\ T 25 S R 2 W \\ 1962 \end{array}$$

from which a new bearing tree and a bearing object

A yew, 15 ins. diam., bears N. $44\frac{1}{2}^{\circ}$ E., 114 lks. dist.,
marked $\frac{1}{4}$ S8 BT.The E. face of a rock outcrop, bears S. 73° W., 20 lks.
dist., marked X BO.Deposit the original corner stone and reset the iron pipe
alongside the iron post.

GENERAL DESCRIPTION

Township 25 south, range 2 west is located about 2 miles in a northeasterly direction from Idleyld Park, Oregon. The township is drained by Rock Creek and its tributaries, draining southerly to the North Umpqua River. Elevation ranges from about 960 feet above sea level at Rock Creek, on the west boundary of section 31 to about 4,648 feet above sea level on Old Fairview Mountain in Section 25.

The main access into the township is by way of a paved road which extends easterly along the north bank of the North Umpqua River, and northerly by way of a graveled road along Rock Creek. Considerable logging has been done on the privately owned lands in the area and a number of logging roads provide good access to most of the lands covered in the remonumentation.

Timber in the area consists of douglas fir, white fir, hemlock, cedar, pine, maple alder, chinquapin, gna yew; undergrowth is of vine maple, huckleberry, poison oak, arrowwood, salmonberry, salal, Oregon grape, and fern.