

County Surveyor's Record, Douglas County, Oregon

-9-

Dependent Resurvey, Subdivisional Lines, T. 32 S., R. 5 W.

CHAINS

from which

A fir, 10 ins. diam., bears S. $32\frac{1}{2}^{\circ}$ E., 19 lks. dist.,
mkd. $\frac{1}{4}$ S CS BT.

A madrone, 18 ins. diam., bears N. $6\frac{3}{4}^{\circ}$ W., 70 lks. dist.,
mkd. $\frac{1}{4}$ S CS BT.

Descend 52 ft. over W. slope.

42.43 Draw, drains SW.; asc. 64 ft. over broken S. slope.

53.45 Spur, clopes S.; desc. 200 ft. over W. slope.

59.94 Point for the W 1/16 sec. cor. of secs. 29 and 32.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins.
in the ground, with brass cap mkd.

W 1/16 $\frac{S\ 29}{S\ 32}$
1962

from which

A madrone, 6 ins. diam., bears N. 31° W., 13 lks.
dist., mkd. W 1/16 S29 BT.

A madrone, 6 ins. diam., bears S. 3° W., 58 lks.
dist., mkd. W 1/16 S32 BT.

Descend 150 ft. over W. slope.

72.09 Dirt road, 25 lks. wide, bears N. and S., curving W. and E.

74.40 Irrigation ditch, 4 lks. wide, drains N.

78.29 Woodford Creek, 6 lks. wide, course N. 20° W.,; asc. 13 ft.
over nearly level land.79.92 The cor. of secs. 29, 30, 31 and 32, perpetuated with an axle
shaft, $1\frac{1}{2}$ ins. diam., firmly set, protruding 8 ins. above
ground at record bearing and distance from the only remaining
original bearing tree;

A sawed fir stump, 42 ins. diam., bears N. 46° E.,
25 lks. dist., mkd. S29 on face of opened blaze.
(mkd. by Thiel in 1904.)

and trees recorded by the Douglas County Surveyor's Office

A cedar, 24 ins. diam., bears N. $20\frac{1}{2}^{\circ}$ E., 110 lks.
dist., with a healed blaze.

✓ A fir, 14 ins. diam., bears S. $46\frac{3}{4}^{\circ}$ E., 63 lks.
dist., with a healed blaze.

An Ash, 12 ins. diam., bears S. 24° W., 151 lks.
dist., mkd. T32S R5W S31 BT.

A fir, 19 ins. diam., bears N. 88° W., 18 lks.
dist., with a healed blaze.

At the corner point

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins.
in the ground, with brass cap mkd.