

County Surveyor's Record, Douglas County, Oregon

-10-

Dependent Resurvey, Subdivisional Lines, T. 32 S., R. 5 W.

CHAINS

T. 32 S R 5 W
 S 30 | S 29
 S 31 | S 32
 1962

from which

- ✓ A fir, 8 ins. diam., bears N. 29° E., 33 lks. dist., mkd. T32S R5W S29 BT.
- ✓ A fir, 14 ins. diam., bears S. 15° E., 47 lks. dist., mkd. T32S R5W S32 BT.
- ✓ A fir, 8 ins. diam., bears S. 12° W., 38 lks. dist., mkd. T32S R5W S31 BT.
- ✓ A fir, 15 ins. diam., bears N. 33° W., 80 lks. dist., mkd. T32S R5W S30 BT.

Land, mountainous.

Soil, clay, loam and rock.

Timber, fir, cedar, madrone, white oak, black oak, live oak, yellow pine, willow, alder, chinquapin and maple; undergrowth, vine maple, salal, arrowwood, manzanita, hazel, poison oak, blackberry, and wild rose.

N. 0° 21' E., bet. secs. 29 and 30.

Descend 24 ft. over gently rolling land, through timber and dense undergrowth.

- 3.00 Woodford Creek, 5 lks. wide, course N. 45° W.; desc. 23 ft. over NE. slope.
- 5.00 Leave creek bottom, asc. 10 ft. over SW. slope.
- 10.60 Leave timber, edge bears S. and W.; thence across meadow.
- 24.00 Dirt road, 20 lks. wide; bears NW. and SE.
- 24.90 Top of ascent, slopes SW.; thence along W. slope.
- 37.00 Dirt road, 15 lks. wide, bears N. 60° E. and S. 60° W.
- 40.54 The original $\frac{1}{4}$ sec. cor. of secs. 29 and 30, perpetuated by the County Surveyor in 1900, monumented with an iron pipe, $\frac{1}{2}$ in. diam., firmly set, protruding 9 ins. above the ground,

from which

- A fir snag, 16 ins. diam., bears S. 74 $\frac{1}{2}$ ° E., 86 lks. dist., mkd. CS $\frac{1}{4}$ S29. (mkd. by Briggs, County Surveyor, in 1900.)
- A fir snag, 18 ins. diam., bears S. 9° W., 94 lks. dist., mkd. 4 S. (mkd. by Briggs, County Surveyor, in 1900.)
- A yellow pine, 28 ins. diam., bears N. 75° W., 56 lks. dist., with a healed blaze. (mkd. by County Surveyor, 1956.)

At the corner point

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.