

County Surveyor's Record, Douglas County, Oregon

-11-

Dependent Resurvey, Subdivisional Lines, T. 32 S., R. 5 W.

CHAINS

T 32 S R 5 W

| | |
|------|------|
| S 30 | S 29 |
| 1962 | |

Fd. OK
 9/85
 BY: Max Hull
 M 99-33
 CS 63/29

from which

A fir, 14 ins. diam., bears S. 84° E., 61 lks. dist.,
mkd., $\frac{1}{4}$ S29 BT.

A fir, 8 ins. diam., bears N. 81° W., 110 lks. dist.,
mkd. $\frac{1}{4}$ S30 BT.

Deposit iron pipe alongside the iron post.

N. 0° 05' W., beginning new measurement.

Descent 45 ft. over NW. slope, changing to N. slope,
through scattering timber and dense undergrowth.

8.30 Barbed wire fence, 4 strand, bears E. and W.; thence over
nearly level agricultural land.

28.85 U. S. Highway No. 99, 70 lks. wide, bears N. 85° E., and
S. 85° W.

36.50 Enter timber, edge bears E. and W.

40.09 Point for the cor. of secs. 19, 20, 29 and 30, at proportionate
distance; there is no remaining evidence of the original
corner.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 26 ins. in
the ground, with brass cap mkd.

| |
|--------------|
| T 32 S R 5 W |
| S 19 S 20 |
| S 30 S 29 |
| 1962 |

SEE M 99-33
 REPORTS CORNER
 & ACCESSORIES
 DESTROYED BY
 CR 11/12

from which

An ash, 22 ins. diam., bears N. 30° E., 22 lks.
dist., mkd. T32S R5W S20 BT.

An ash, 9 ins. diam., bears S. 48 $\frac{1}{2}$ ° E., 34 lks.
dist., mkd. T32S R5W S29 BT.

An ash, 18 ins. diam., bears N. 68 $\frac{1}{2}$ ° W., 65 lks.
dist., mkd. T32S R5W S19 BT.

From this point an iron pipe, 1 $\frac{1}{2}$ ins. diam., firmly set,
protruding 14 ins. above ground, bears S. 22° W., 0.135 chs.
distance.

from which locally established bearing trees

An alder, 14 ins. diam., bears S. 71 $\frac{1}{4}$ ° E., 29 lks.
dist., with a partially healed blaze.

An alder, 20 ins. diam., bears S. 52 $\frac{1}{4}$ ° W., 90 lks.
dist., with a partially healed blaze.

An alder, 24 ins. diam., bears N. 57 $\frac{1}{4}$ ° W., 43 lks.
dist., with a partially healed blaze.