

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 32 S., R. 5 W.

CHAINS

T 32 S R 5 W
W P
S 19
S 30
1962

from which

A yellow pine, 17 ins. diam., bears N. 33° W., 93 lks. dist., mkd. S19 WP BT.

A white oak, 22 ins. diam., bears S. 69° E., 121 lks. dist., mkd. S30 WP BT.

Land, nearly level.

Soil, clay loam.

Timber, fir, cedar, madrone, yellow pine, chinquapin, maple, ash and alder; undergrowth, arrowwood, hazel, poison oak, and live oak.

From the corner of secs. 20, 21 28 and 29.

N. 89° 37' W., bet. secs. 20 and 29.

Over nearly level land, through scattering timber and dense undergrowth.

15.35 U. S. Highway No. 99, 70 lks. wide, bears N. 71° E. and S. 71° W.

40.45 The 1/4 sec. cor. of secs. 20 and 29, determined from the only remaining original bearing tree:

A cottonwood, 14 ins. diam., bears S. 15° E., 26 lks. dist., mkd. BT.

At the corner point

Set an iron post, 30 ins. long, 2 1/2 ins. diam., 26 ins. in the ground with brass cap mkd.

T 32 S R 5 W
1/4 S20
S 29
1962

SEE M99-33
REPORTS CORNER
+ ACCESSORIES DESTROYED
BY COW CREEK
9/85

from which

A cottonwood, 8 ins. diam., bears N. 52 1/2° W., 34 lks. dist., mkd. 1/4 S20 BT.

A maple, 7 ins. diam., bears S. 10 1/2° E., 40 lks. dist., mkd. 1/4 S29 BT.

An iron pipe, 1 in. diam., firmly set, bears S. 59° E., 32 lks. dist.

N. 89° 37' W., beginning new measurement.

Over nearly level land, through scattering timber and dense undergrowth.

39.93 The corner of secs. 19, 20, 29 and 30e

Land, nearly level.

Soil, sand and clay loam.

Timber, fir, cedar, madrone, yellow pine, chinquapin, maple, ash and alder; undergrowth, arrowwood, hazel, poison oak, and live oak.

Dist., mkd. BT.