

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Line bet. Secs. 3 and 4, T. 23 S., R. 4 W..

CHAINS

partial scribe mks., on an opened blaze.
(Record bearing, N. 15° E.)

A fir snag, 45 ins., diam., bears N. 39° W., 44
lks. dist., mkd. T23S R4W S4 BT, in the bark.
(Record bearing, N. 45° W.)

and trees marked by Wilford N. Haines, Professional Land
Surveyor, in June, 1961:

A fir, 6 ins. diam., bears N. 35° E. 17 lks.
dist., mkd. T23S R4W S3 BT, on a healing blaze.

A maple, 13 ins. diam., bears S. 5° W., 25 lks.
dist., mkd. 363 T23S R4W S9 BT, on open blaze.

A fir, 8 ins. diam., bears S. 59° W., 20 lks.
dist., mkd. with a healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins.
in the ground, with brass cap marked

T 23 S R 4 W	
S 4 S 3	
S 9 S 10	
1963	

from which a new bearing tree:

A fir, 14 ins. diam., bears S. 25° E., 153 lks.
dist., mkd. T23S R4W S10 BT.

No suitable tree in sec. 4 within limits.

From this point, a point established by Haines bears
S. 80° E., 6 lks. dist., monumented with a ¾ in. "T"
iron, protruding 12 in. above ground, firmly set, with
a brass disc, ¾ in. diam., on top, mkd. Wilford N.
Haines Drain Ore. 239 Survey Point. There appears to be
no basis for the corner to be in this position.

N. 0° 10' E., bet. secs. 3 and 4, marking and blazing
the true line.

Ascend 225 ft. over precipitous SE. slope, through heavy
timber and moderate undergrowth.

11.00 Spur, slopes SW.; asc. 10 ft. along W. slope.

18.10 Slope changes; desc. 10 ft. over N. slope.

19.98 Point for the S 1/16 sec. cor. of secs. 3 and 4.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins.
in the ground, with brass cap marked

S 1/16	
S 4 S 3	
T 23 S R 4 W	
1963	

from which

A fir, 25 ins. diam., bears S. 71¼° E., 32 lks.
dist., mkd. S 1/16 S3 BT.

A fir, 12 in. diam., bears S. 28½° W., 88 lks.