

County Surveyor's Record, Douglas County, Oregon

Remonumentation, Original Corner Points, T. 23 S., R. 4 W.

CHAINS

(Remonumenting a corner established by
James Freeman, in 1851)

The cor. of secs. 19, 24, 25 and 30, on the W. bdy, of
T. 23 S., R. 4 W., determined at record bearing and dis-
tance from the remains of the original bearing trees:

A yew, 12 ins. diam., down and rotted, bears
N. $26\frac{1}{2}^{\circ}$ E., 39 lks. dist., mkd. with a rotted
blaze and old axe marks.

A fir stump hole, bears S. 15° E., 12 lks. dist.

A rotted fir stump, 20 ins. diam., bears S. 23° W.,
21 lks. dist., with no marks remaining.

A rotted fir stump, 24 ins. diam., bears N. $44\frac{1}{2}^{\circ}$
W., 63 lks. dist., mkd. with a rotted blaze.

and an original line tree:

A fir, 55 ins. diam., bears North, 30 lks. dist.,
mkd. with two hacks each on N. and S. sides.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 21 ins.
in the ground, with brass cap marked

T 23 S	
R 5 W	R 4 W
S 24	S 19
S 25	S 30
1963	

from which new bearing trees:

A yew, 8 ins. diam., bears N. $43\frac{1}{4}^{\circ}$ E., 54 lks.
dist., mkd. T23S R4W S19 BT.

A fir, 10 ins. diam., bears S. $22\frac{1}{2}^{\circ}$ E., 146 lks.
dist., mkd. T23S R4W S30 BT.

A yew, 15 ins. diam., bears S. 68° W., 25 lks.
dist., mkd. T23S R5W S25 BT.

A fir, 15 ins. diam., bears S. 53° W., 44 lks.
dist., mkd. T23S R5W S24 BT.

(Remonumenting corners established by
Harvey Gordon and Charles T. Gardner, in 1855)

The cor. of secs. 20, 21, 28 and 29, determined at the
intersection of very old and fallen fences which bear
N., S., E., and W., from which unrecorded bearing trees

A cedar, 32 ins. diam., bears N. 12° E., 106 lks.
dist., mkd. S21 T23S R4W, on opened blaze.

A cedar, 32 ins. diam., bears S. 73° W., 273 lks.
dist., mkd. with a healed double blaze.
Reblazed on the overgrowth and mkd. T23S R4W S29
BT.

At the corner point