

## County Surveyor's Record, Douglas County, Oregon

Remonumentation, Original Corner Points, T. 23 S., R. 4 W.

CHAINS

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap marked

T 23 S R 4 W

S 20 | S 21

S 29 | S 28

1963

TO BE REMOVED  
SEE CO. SURV. BRASS CAP, 1966  
REN. NO. 143

from which a new bearing tree:

A cedar, 8 ins. diam., bears N.  $76\frac{1}{2}^{\circ}$  W., 139 lks. dist., mkd. T23S R4W S20 BT.

No suitable tree available in section 28.

The corner is situated on a SE. slope, 40 lks. W. of a new wire fence which bears N. and S.

The  $\frac{1}{4}$  sec. cor. of secs. 31 and 32, perpetuated by persons unknown with a quarried granite stone, 16 x 8 x 6 ins. above ground, firmly set, from which the remains of the original bearing trees:

A oak stump hole, bears N.  $55^{\circ}$  E., 51 lks. dist.

An oak stump hole, bears S.  $56^{\circ}$  W., 40 lks. dist.

At the corner point

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, against the W. side of the quarried stone, with brass cap marked

S 31 |  $\frac{1}{4}$  S 32

T 23 S | R 4 W

1963

from which new bearing trees:

A cedar, 12 ins. diam., bears N.  $65\frac{1}{2}^{\circ}$  E., 355 lks. dist., mkd.  $\frac{1}{4}$  S32 BT.

A fir, 10 ins. diam., bears S.  $85^{\circ}$  W., 235 lks. dist., mkd.  $\frac{1}{4}$  S31 BT.

The corner is situated in open pasture, at the N. side of the top of a spur which slopes NW.

The  $\frac{1}{4}$  sec. cor. of secs. 29 and 30, determined at record bearing and distance from bearing trees mkd. by Arthur Boyer, Deputy County Surveyor, in 1943, when he reestablished the corner from the original SW. bearing tree, a cherry, which was still in evidence at that time:

A cedar, 12 ins. diam., dead and fallen, bears S.  $55^{\circ}$  E., 26 lks. dist., mkd. BT on a burned blaze.

A fir, 30 ins. diam., fallen, bears N.  $10^{\circ}$  W., 15 lks. dist., with blaze on underside of tree.

At the corner point