

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, South Boundary, T. 24 S., R. 2 W.

CHAINS

S. 80° 35' W., bet secs. 2 and 35.

Descend 360 ft. over NW. slope, through heavy timber and dense undergrowth.

9.69 Rock Creek, 175 lks. wide, course S. 40° W.; asc. 35 ft. over SE. slope.

13.44 Trail, bears S. 20° W. and N. 40° E.

14.93 Top of ascent, desc. 7 ft. over SW. slope.

15.20 Branch, 2 lks. wide, course S. 80° E.; asc. 649 ft. over E. slope.

30.43 Ridge, bears N. 40° W. and S. 20° E.; desc. 220 ft. over W. slope.

37.81 Point for the 1/4 sec. cor. of sec. 35, at proportionate distance; there is no remaining evidence of the original corner. This now becomes the 1/4 sec. cor. of secs. 2 and 35.

Set an iron post, 36 ins. long, 1 in. diam., 28 ins. in the ground, with brass cap mkd.

1/4 S 35  
S 2  
1951

from which bearing trees marked in 1963:

A hemlock, 11 ins. diam., bears N. 33 1/4° E., 101 lks. dist., mkd. 1/4 S35 BT.

A fir, 11, ins. diam., bears S. 19 3/4° W., 82 lks. dist., mkd. 1/4 S2 BT.

Descend 167 ft. along broken S. slope.

59.43 Graded and graveled logging road, bears N. 40° W., and S. 70° E.

62.57 Creek, 14 lks. wide, course S. 80° E.; asc. 98 ft. over NE. slope.

67.98 Branch, 1 lk. wide, course N.; asc. 107 ft. over N. slope.

75.62 Point for the cor. of secs. 34 and 35, at proportionate distance; there is no remaining evidence of the original corner. This now becomes the cor. of secs. 2, 3, 34, and 35.

Set an iron post, 36 ins. long, 2 ins. diam., 28 ins. in the ground, with brass cap mkd.

T 24 S | R 2 W  
S 34 | S 35  
S 3 | S 2  
T 25 S  
1951

from which

A cedar, 15 ins. diam., bears N. 45 1/2° E., 92 lks. dist., mkd. T24S R2W S35 BT. (1963 bearing tree.)