

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, South Boundary, T. 24 S., R. 2 W.

CHAINS

A cedar, 20 ins. diam, bears N. 40° E., 39 lks.
dist., mkd. T24S R2W S34 BT. (1951 bearing tree.)

A hemlock, 6 ins. diam,, bears S. 32° E., 53 lks.
dist., mkd. T25S R2W S3 BT. (1963 bearing tree.)

A chinquapin, 16 ins. diam., bears S. $64\frac{1}{4}^{\circ}$ W.,
33 lks. dist., mkd. T25S R2W S4 BT. (1963
bearing tree.)

A fir, 26 ins. diam., bears N. $46\frac{1}{2}^{\circ}$ W., 69 lks.
dist., mkd. T24S R2W S33 BT. (1951 bearing tree.)

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, hemlock, sugar pine, cedar, maple, yew,
and madrone; undergrowth, vine maple, salal, huckle-
berry, and Oregon grape.

S. 80° 35' W., bet., secs. 4 and 33.

Descend 100 ft. over SW. slope, through heavy timber and
dense undergrowth.

2.90 Creek, 10 lks. wide, course S. 15° E.; asc. 225 ft. over
SE. slope.

10.00 Spur, slopes S. 15° E.; desc. 125 ft. over SW. slope.

17.30 Foot of descent, slopes SW.; asc. 20 ft. over SE. slope.

18.30 Top of ascent, slopes S.; desc. slightly along S. slope

18.90 Point for the NW. cor. of Tract No. 37, in sec. 4, T.
25 S., R. 2 W.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. dia ., 22 ins.
in the ground, with brass cap mkd.

T 24 S R 2 W

S 33

TR 37

S 4 | TR 37

T 25 S | R 2 W

1963

from which

A hemlock, 12 ins. diam., bears N. 7° W., 29 lks.
dist., mkd. TR37 S33 BT.

A cedar, 30 ins. diam., bears S. $82\frac{1}{4}^{\circ}$ E., 92 lks.
dist., mkd. TR37 S4 BT.

Descend 120 ft. along S. slope, changing to SW. slope.

27.00 Creek, 30 lks. wide, course S. 20° E.; asc. 38 ft.
over SE. slope.

37.81 Point for the $\frac{1}{4}$ sec. cor. of sec. 33, at proportionate
distance; there is no remaining evidence of the original
corner. This now becomes the $\frac{1}{4}$ sec. cor. of secs. 4
and 33.

Set an iron post, 36 ins. long, 1 in. diam., 28 ins. in
the ground, with brass cap mkd.