

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, South Boundary, T. 24 S., R. 2 W.

CHAINS

A broken hemlock, 14 ins. diam., bears N. 56° W.,
50 lks. dist., mkd. T24 R2 S31 BT. (Record
bearing, N. 60° W.)

At the corner point

Set an iron post, 36 ins. long, 2 ins. diam., 20 ins.
in the ground to solid rock and in a mound of stone, 4
ft. base, to top, with brass cap mkd.

T 24 S	R 2 W
S 31	S 32
S 6	S 5
T 25 S	
1951	

from which new bearing trees:

A hemlock, 9 ins. diam., bears S. 68° E., 91 lks.
dist., mkd. T25S R2W S5 BT. (1963 bearing tree.)

A yew, 7 ins. diam., bears S. $86\frac{1}{2}^{\circ}$ W., 40 lks.
dist., mkd. T25S R2W S6 BT. (1963 bearing tree.)

A hemlock, 16 ins. diam., bears N. $12\frac{1}{4}^{\circ}$ W., 85
lks. dist., mkd. T24S R2W S31 BT. (1951 bearing
tree.)

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, hemlock, sugar pine, cedar, yew, madrone,
maple, and dogwood; undergrowth, vine maple, salal,
huckleberry, and Oregon grape.

N. 88° 39' W., bet. secs. 6 and 31.

Descend 25 ft. over SW. slope, along S. edge of logging.

0.80 Branch, 4 lks. wide, course SE.; asc. 32 ft. over SE.
slope.

2.15 Top of ascent; desc. 6 ft. over SW. slope.

3.25 Ravine, course SE.; asc. 247 ft. SE. slope.

34.95 Top of ascent; desc. 52 ft. over SW. slope.

37.80 Branch, 3 lks. wide, course SE.; asc. 60 ft. over SE.
slope.

39.66 The $\frac{1}{4}$ sec. cor. of sec. 31 only, determined from the
remains of the original bearing trees:

A sawed fir stump, 48 ins. diam., bears S. 35°
E., 28 lks. dist., with partial scribe marka
on old bark blaze.

A fallen dogwood, 8 ins. diam., bears N. 26° W., 18
lks. dist., with blaze healed. (Record bearing,
N. 20° W.)

At the corner point

Set an iron post, 36 ins. long, 1 in. diam., 20 ins.
in the ground to solid rock and in a mound of stone, 4
ft. base to top, with brass cap mkd.