

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, South Boundary, T. 24 S., R. 2 W.

CHAINS

$$\frac{1}{4} S 31$$

$$1951$$

from which bearing trees mkd. in 1951:

A yew, 6 ins. diam., bears N. $1^{\circ} 45'$ E., 108 lks. dist., mkd. $\frac{1}{4}$ S31 BT.

A fir, 48 ins. diam., bears N. $54\frac{1}{2}^{\circ}$ W., 82 lks. dist., mkd. $\frac{1}{4}$ S31 BT.

N. $78^{\circ} 59'$ W., beginning new measurement.

Ascend 72 ft. over E. slope, across logged off land.

7.92 A spur, slopes, S.; desc. 43 ft. over SW. slope.

15.50 Branch, 4 lks. wide, course SE.; asc. 398 ft. over SE. slope.

25.00 Graded and graveled logging road, bears N. 60° E. and S. 60° W.

29.00 Graded and graveled logging road, bears N. 65° E. and S. 65° W.

35.10 Top of ascent; desc. 34 ft. over W. slope.

36.73 Branch, 4 lks. wide, course S.; asc. 9 ft. over SE. slope.

37.07 The cor. of Tps. 24 and 25 S., Rs. 2 and 3 W. In 1951 the iron post set in 1943 has been displaced in logging operations and is found lying on the surface; the original NE. bearing tree is gone.

At the corner point

Reset the iron post, 36 ins. long, 3 ins. diam., 20 ins. in the ground to solid rock, and in a mound of stone, 4 ft. base to top, with brass cap mkd.

$$\begin{array}{c} T 24 S \\ R 3 W | R 2 W \\ S 36 | S 31 \\ \hline S 1 | S 6 \\ T 25 S \end{array}$$

from which

A fir, 50 ins. diam., bears N. $77\frac{1}{2}^{\circ}$ E., 252 lks. dist., mkd. T24S R2W S31 BT. (1951 bearing tree.)

A dead fir, 50 ins. diam., bears S. $13\frac{1}{2}^{\circ}$ E., 38 lks. dist., with blaze burnt. (1943 bearing tree; record bearing, S. $18\frac{1}{2}^{\circ}$ E.)

A dead hemlock, 14 ins. diam., bears S. $7\frac{1}{2}^{\circ}$ E., 37 lks. dist., with blaze burnt. (Original bearing tree; 1943 record bearing, S. $11\frac{1}{4}^{\circ}$ E.)

A dead hemlock, 20 ins. diam., bears S. $20\frac{1}{2}^{\circ}$ W., 19 lks. dist., with blaze burnt. (Original bearing tree.)