

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T.24 S., R. 2 W.

CHAINS

0.45 Point for the NE. cor. of Tract No. 38, sec. 34.
Set an iron post, 36 ins. long, 2 ins. diam., 28 ins. in the ground, with brass cap mkd.

T 24 S R 2 W
S 34 | S 35
TR 38 | TR 39
1963

from which

A hemlock, 12 ins. diam., bears N. $3\frac{1}{4}^{\circ}$ E., 86 lks. dist., mkd. S34 BT.

A hemlock, 9 ins. diam., bears S. $65\frac{1}{2}^{\circ}$ W., 58 lks. dist., mkd. TR38 S34 BT.

Descend 146 ft. over NE. slope.

7.25 N. channel of creek, 10 lks. wide, course S. 85° E.; asc. 175 ft. over S. slope.

11.10 Graded and graveled logging road, bears N. 50° W. and S. 80° E.

14.44 Point for the NW. cor. of Tract No. 39, sec. 35.

Set an iron post, 36 ins. long, 2 ins. diam., 28 ins. in the ground, with brass cap mkd.

T 24 S R 2 W
S 34 | S 35
TR 39
1963

from which

A sugar pine, 9 ins. diam., bears N. $34\frac{1}{4}^{\circ}$ E., 53 lks. dist., mkd. S35 BT.

A fir, 15 ins. diam., bears S. $39\frac{1}{4}^{\circ}$ E., 62 lks. dist., mkd. TR39 S35 BT.

Ascend 120 ft. over S. slope.

21.80 Spur, slopes S. 40° W.; desc. 15 ft. over broken NW. slope.

24.90 Foot of descent; asc. 110 ft. over broken SW. slope.

29.90 The $\frac{1}{4}$ sec. cor. of secs. 34 and 35, monumented with a basalt stone, 10x 9 x 8 ins.; firmly set, marked $\frac{1}{4}$ on W. face, from which the original bearing trees:

A chinquapin, 6 ins. diam., bears N. 71° W., 7 lks. dist., with blaze rotted out. (In 1951) (Record bearing, N. 56° W.) This tree has disappeared by 1963.

A pine, 14 ins. diam., bears S. $39\frac{1}{4}^{\circ}$ E., 42 lks. dist., blaze partially healed and has been cut open, with scribe mark 4 visible. (Record bearing, S. 39° E.)

At the corner point

Set an iron post, 36 ins. long, 1 in. diam., 28 ins. in the ground, with brass cap mkd.