

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 24 S., R. 2 W.

CHAINS

$$\begin{array}{c} \frac{1}{4} \\ \hline S\ 34 \mid S\ 35 \\ 1951 \end{array}$$

from which

A fir, 15 ins. diam., bears N. $10\frac{1}{2}^{\circ}$ W., 146 lks. dist., mkd. $\frac{1}{4}$ S34 BT. (1963 bearing tree.)

A fir, 14 ins. diam., bears S. 83° E., 67 lks. dist., mkd. $\frac{1}{4}$ S35 BT. (1951 bearing tree, 20 ins. diam., with blaze healed, in 1963.)

Bury the original corner stone alongside the iron post.

N. 0° 15' E., beginning new measurement.

Ascend 256 ft. over SW. slope.

10.36 Ravine, course W.

16.60 Spur, slopes W.; desc. 12 ft. over NW. slope.

18.60 Foot of descent; asc. 161 ft. over SW. slope.

29.26 Spur, slopes W.

32.58 Spur, slopes SW.; desc. 7 ft. over NW. slope.

34.58 Ravine, course NE.; asc. 95 ft. over S. slope.

39.47 The cor. of secs. 26, 27, 34, and 35, determined at record distance from the original bearing trees:

A hemlock, 30 ins. diam., bears N. $16\frac{1}{2}^{\circ}$ E., 30 lks. dist., blaze healed and has been cut open, scribe marks S26 visible. (Record bearing, N. 19° E.)

A hemlock, 20 ins. diam., bears S. $31\frac{1}{4}^{\circ}$ E., 65 lks. dist., blaze partially healed, scribe marks 35 visible. (Record, a fir, bears S. 30° E.)

A cedar, 28 ins. diam., bears S. $26\frac{1}{2}^{\circ}$ W., 29 lks. dist., blaze partially healed, with scribe marks 2W S34 visible. (Record bearing, S. 21° W.)

A cedar, 26 ins. diam., bears N. $9\frac{1}{2}^{\circ}$ W., 24 lks. dist., blaze healed. (Record bearing, N. 8° W.)

At the corner point

Set an iron post, 36 ins. long; 2 ins. diam., 28 ins. in the ground, with brass cap mkd.

$$\begin{array}{c} T\ 24\ S \mid R\ 2\ W \\ \hline S\ 27 \mid S\ 26 \\ \hline S\ 34 \mid S\ 35 \\ 1951 \end{array}$$

No new accessories established; cor. on spur, slopes South.