

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 24 S., R. 2 W.

CHAINS	Land, mountainous. Soil, rocky clay loam. Timber, fir, hemlock, cedar, sugar pine, yew, madrone, chinquapin, and dogwood; undergrowth, vine maple, salal, huckleberry, and Oregon grape.
	From the cor. of secs. 25, 26, 35, and 36. N. 89° 51' W., bet. secs. 26 and 35. Descend 103 ft. over W. slope, through heavy timber and dense undergrowth.
3.40	Trail, bears N. and S.
6.41	Rock Creek, 80 lks. wide, course S. 10° E.; asc. 655 ft. over E. slope.
22.31	Spur, slopes N.; asc. 29 ft. over broken N. slope.
33.69	The $\frac{1}{4}$ sec. cor. of secs. 26 and 35, determined from the remains of the original bearing trees. A fallen fir, 18 ins. diam., bears N. 52° E., 22 lks. dist., blaze healed, edge of face under 56 yrs. of overgrowth, down for approximately a year. A fallen cedar, 18 ins. diam., bears S. 70° W., 36 lks. dist., blaze healed. At the corner point Set an iron post, 36 ins. long, 1 in. diam., 28 ins. in the ground, with brass cap mkd. $\frac{1}{4} \begin{array}{l} S 26 \\ S 35 \end{array}$ from which 1951 A fir, 26 ins. diam., bears N. 42° 45' E., 102 lks. dist., mkd. $\frac{1}{4}$ S26 BT. A fir, 40 ins. diam., bears S. 14 $\frac{1}{2}$ ° E., 98 lks. dist., mkd. $\frac{1}{4}$ S35 BT. <hr/> N. 89° 47' W., beginning new measurement. Ascend 76 ft. over SE. slope.
11.40	Top of ascent; desc. 3 ft. over NW. slope.
11.90	Ravine, course NE.; asc. 170 ft. over NE. slope.
23.37	Spur, slopes NW.; desc. 28 ft. over NW. slope.
25.58	Ravine, course N.; asc. 93 ft. over NE. slope.
28.87	Spur, slopes NE.; desc. 54 ft. over N. slope.
32.81	Branch, 1 lk. wide, course N. 45° E.; asc. 261 ft. over NE. slope.
39.98	The cor. of secs. 26, 27, 34, and 35.