

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 24 S., R. 2 W.

CHAINS

from which

A hemlock, 22 ins. diam., bears N. $9\frac{1}{4}^{\circ}$ E., 84 lks.
dist., mkd. T24S R2W S27 BT.

A hemlock, 20 ins. diam., bears S. $33\frac{1}{4}^{\circ}$ W., 43 lks.
dist., mkd. T24S R2W S33 BT.

Bury the original corner stone alongside the iron
post.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, hemlock, cedar, sugar pine, yew, madrone,
chinquapin, and dogwood; undergrowth, vine maple,
salal, huckleberry, and Oregon grape.

From the cor. of secs. 26, 27, 34, and 35.

N. $89^{\circ} 02'$ W., bet. secs. 27 and 34.

Descend 238 ft. over SW. slope, through heavy timber and
dense undergrowth.

19.24 Branch, 1 lk. wide, course S. 10° W.; asc. 66 ft. over
E. slope.

24.14 Spur, slopes S.; desc. 37 ft. over SW. slope.

25.50 Graded and graveled logging road, bears N. and S.

27.43 Branch, 1 lk. wide, course S.; asc. 48 ft. over E.
slope.

30.32 Spur, slopes S.; desc. 56 ft. over W. slope.

32.37 Branch, 1 lk. wide, course SW.; asc. 81 ft. over S.
slope.

39.59 The $\frac{1}{4}$ sec. cor. of secs. 27 and 34, determined at
record distance from the original bearing trees:

A cedar, 12 ins. diam., bears N. $45\frac{1}{4}^{\circ}$ E., 27 lks.
dist., blaze healed. (Record bearing, N. 44° E.)

A cedar, 8 ins. diam., bears S. 67° E., 26 lks.
dist., scribe marks $\frac{1}{4}$ S BT visible. (Record
bearing, S. 68° E.)

At the corner point

Set an iron post, 36 ins. long, 1 in. diam., 28 ins.
in the ground, with brass cap mkd.

$$\frac{1}{4} \begin{array}{l} \text{S } 27 \\ \text{S } 34 \\ 1951 \end{array}$$

from which

A fir, 14 ins. diam., bears N. $54\frac{1}{2}^{\circ}$ E., 64 lks.
dist., mkd. $\frac{1}{4}$ S27 BT.

A hemlock, 12 ins. diam., bears S. $55\frac{1}{2}^{\circ}$ E., 50 lks.
dist., mkd. $\frac{1}{4}$ S34 BT.