

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 24 S., R. 2 W.

CHAINS	
	N. 21° 19' E., bet. secs. 28 and 29.
	Descend 221 ft. over NE. slope, through heavy timber and dense undergrowth.
12.84	Branch, 4 lks. wide, course SE.; asc. 415 ft. over S. slope.
36.05	The $\frac{1}{4}$ sec. cor. of secs. 28 and 29, determined at record distance from the original bearing trees:
	A hemlock, 36 ins., diam., bears N. 40° E., 16 lks. dist., blaze partially healed, scribe marks $\frac{1}{4}$ S visible.
	A fir, 30 ins. diam., bears N. 53 $\frac{1}{2}$ ° W., 32 lks. dist., blaze healed, lower blaze cut open, shows the scribe marks BT under 68 years of overgrowth. (Record bearing, N. 50° W.)
	At the corner point
	Set an iron post, 36 ins. long, 1 in. diam., 28 ins. in the ground, with brass cap mkd.
	$\begin{array}{c} \frac{1}{4} \\ \text{S } 29 \left \text{S } 28 \\ 1951 \end{array}$
	No new accessories established.
	Land, mountainous.
	Soil, rocky clay loam.
	Timber, fir, hemlock, cedar, sugar pine, yew, madrone, chinquapin, and dogwood; undergrowth, vine maple, salal, huckleberry, Oregon grape, and rhododendron.
	From the cor. of secs. 5, 6, 31 and 32, on the S. bdy. of the Tp.
	N. 1° 36' E., bet. secs. 31 and 32.
	Ascend 22 ft. over S. slope, across logged land.
2.26	Top of ascent; desc. 6 ft. over N. slope.
3.36	Ravine, course E.; asc. 131 ft. over broken S. slope.
7.68	Graded and graveled road, bears E. and W.
19.85	Top of ascent; desc. 29 ft. over broken N. slope.
26.89	Branch, 4 lks. wide, course E.; asc. 26 ft. over SW. slope.
29.26	Branch, 6 lks. wide, course SE.; asc. 128 ft. over SW. slope.
29.80	Graded and graveled logging road, bears E. and W., washed out E. of this point.
39.31	The $\frac{1}{4}$ sec. cor. of secs. 31 and 32, determined at record bearing and distance from the original SE. bearing trees:
	A dead hemlock, 18 ins. diam., bears S. 65° E., 55 lks. dist., scribe marks $\frac{1}{4}$ S visible in