

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of Subdivisional Lines, T. 24 S., R. 8 W.

CHAINS

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 15 ins. in the ground, to solid rock, and in a mound of stone, 3 ft. base, to top, with brass cap marked

$$\begin{array}{c} \frac{1}{4} \\ \text{S } 28 \text{ | } \text{S } 27 \\ \text{T } 24 \text{ S | R } 8 \text{ W} \\ 1962 \end{array}$$

from which new bearing trees:

A hemlock, 12 ins. diam., bears S. 42° E., 38 lks. dist., mkd. $\frac{1}{4}$ S27 BT.

A hemlock, 14 ins. diam., bears N. 67° W., 73 lks. dist., mkd. $\frac{1}{4}$ S28 BT.

N. 0° 11' E., beginning new measurement.

Descend 170 ft. over NE. slope.

- 4.45 Creek, 1 lk. wide, course N. 30° W.; asc. 5 ft. along W. slope.
- 5.30 Point of Spur, slopes N. 60° W.; desc. 60 ft. over NW. slope.
- 6.70 Miner Creek, 20 lks. wide, course N. 75° E.; asc. 640 ft. over S. slope.
- 25.80 Spur ridge, bears N. 60° W. and S. 60° E.; desc. 335 ft. over NE. slope.
- 36.15 Creek, 8 lks. wide, course S. 75° E.; asc. 215 ft. over S. slope.
- 41.10 Top of ascent, slopes S. 75° W.; desc. 2 ft. along W. slope.
- 41.95 Draw, drains S. 60° W.; asc. 2 ft. over S. slope.
- 42.08 The cor. of secs. 21, 22, 27 and 28, monumented with an iron post, $2\frac{1}{2}$ ins. diam., firmly set, with brass cap mkd. and witnessed as described in the official record.
- Land, mountainous.
Soil, rocky clay.
Timber; fir, hemlock, madrone, maple, cedar, alder, dogwood, chinquapin and yew; undergrowth; young timber, salal, hazel, arrowwood, Oregon grape, huckleberry, fern and poison oak.
-
- N. 1° 33' W., bet. secs. 21 and 22.
- Ascend 60 ft. over SW. slope, through heavy timber and moderate undergrowth.
- 7.30 Creek bog, 4 lks. wide, course S. 45° W.; asc. 300 ft. over SW. slope.
- 24.70 Bateman Lookout Road, 25 lks. wide, bears N. 40° W. and S. 40° E.
- 32.15 Spur, slopes N. 85° W.; desc. 200 ft. over NW. slope.
- 37.25 Dirt road, 20 lks. wide, bears N. 15° E. and S. 35° W.