

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 24 S., R. 8 W.

CHAINS	
	N. 2° 53' W., beginning new measurement. Ascend 10 ft. along E. slope.
0.76	Bateman Lookout Road, 20 lks. wide, bears N. 80° E. and S. 30° W.
1.05	Ridge, bears N. 75° E. and S. 30° W. (Old blazed trail follows top of ridge); desc. 50 ft. along W. slope.
8.60	Spur, slopes N. 30° W.; desc. 440 ft. over NE. slope.
23.65	Creek, 5 lks. wide, course N. 75° W.; asc. 10 ft. along broken W. slope.
36.10	Creek, 3 lks. wide, course S. 50° W.; asc. 20 ft. over SE. slope.
37.72	The cor. of secs. 19, 20, 29 and 30, monumented with an iron post, 2½ ins. diam., firmly set, with brass cap mkd. and witnessed as described in the official record. Land, mountainous. Soil, rocky clay, loam. Timber, fir, hemlock, cedar, madrone, alder, maple and chinquapin; undergrowth, young timber, salal, rhododendron, Oregon grape, hazel, arrowwood, vine maple, huckleberry, poison oak, and ferns.
	From the cor. of secs. 20, 21, 28 and 29. S. 86° 41' W., bet. secs. 20 and 29. Ascend 90 ft. along broken S. slope, through heavy timber and moderate undergrowth.
14.40	Top of ascent, slopes S.; desc. 45 ft. along nearly level S. slope.
27.00	Slope changes; desc. 150 ft. over SW. slope.
31.35	Creek, 4 lks. wide, course S. 30° E.; asc. 175 ft. over NE. slope.
41.43	The ¼ sec. cor. of secs. 20 and 29, determined at record bearing and distance from the original bearing trees: A downed fir, bears N. 11° W., 38 lks. dist., no marks visible. A hemlock, 22 ins. diam., bears S. 18½° E., 6 lks. dist. mkd. with a healed blaze and cruiser mks. Reblaze and mark ¼ S29 BT. At the corner point Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap marked $\frac{1}{4} \frac{S \ 20}{S \ 29}$ T 24 S R 8 W 1962 from which a new bearing tree A fir, 12 ins. diam., bears N. 12½° E., 76 lks. dist., mkd. ¼ S20 BT.