

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, East Boundary, T. 25 S., R. 2 W.

CHAINS

Land, mountainous.
Soil, rocky clay loam.
Timber, fir, hemlock, sugar pine, cedar, maple, yew, madrone, dogwood, and chinquapin; undergrowth, vine maple, salal, huckleberry, Oregon grape, and rhododendron.

N. 0° 18' W., along the E. bdy. of sec. 1.

Ascend 315 ft. over S. slope, through heavy timber and dense undergrowth.

20.39 Spur, slopes S. 20° E.; desc. 212 ft. over broken N. slope.

40.66 Point for the $\frac{1}{4}$ sec. cor. of sec. 1 only, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 36 ins. long, 1 in. diam., 28 ins. in the ground, with brass cap mkd.

$$\begin{array}{r} \frac{1}{4} \\ S \ 1 \\ \hline 1951 \end{array}$$

from which

A hemlock, 26 ins. diam., bears N. 12° 45' W., 49 lks. dist., mkd. $\frac{1}{4}$ S1 BT.

A hemlock, 16 ins. diam., bears S. 28° W., 66 lks. dist., mkd. $\frac{1}{4}$ S1 BT.

Ascend 201 ft. over broken E. slope.

65.70 Top of ascent; desc. 204 ft. over broken E. slope.

81.24 Foot of descent; asc. 143 ft. over broken E. slope.

94.82 Top of ascent; desc. 17 ft. over broken N. slope.

96.69 Ravine, course S. 75° E.; asc. 130 ft. over broken E. slope.

115.27 Intersect the S. bdy. of Tp. 24 S., R. 1 W.

Proportionate point for the closing cor. of Tps. 25 S., Rs. 1 and 2 W.

Set an iron post, 36 ins. long, 3 ins. diam., 28 ins. in the ground, with brass cap mkd.

$$\begin{array}{r} T \ 24 \ S \ R \ 1 \ W \\ S \ 31 \\ \hline S \ 1 \ S \ 6 \\ R \ 2 \ W \ R \ 1 \ W \\ T \ 25 \ S \\ CC \\ 1951 \end{array}$$

from which

A fir, 30 ins. diam., bears S. $41\frac{1}{4}^{\circ}$ E., 42 lks. dist., mkd. T25S R1W S6 CC BT.

A fir, 26 ins. diam., bears S. 74° 45' W., 19 lks. dist., mkd. T25S R2W S1 CC BT.