

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, East Boundary, T. 25 S., R. 2 W.

CHAINS

From the point of intersection the SW. cor. of T. 24 S., R. 1 W., bears S. 89° 51' W., 13.97 chains dist., heretofore described.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, hemlock, sugar pine, cedar, maple, yew, madrone, dogwood, and chinquapin; undergrowth, vine maple, salal, huckleberry, Oregon grape, and rhododendron.

Resurvey of a Portion of the Subdivisional Lines of T. 25 S., R. 2 W.

(Restoring the 1900 survey by Hezekiah H. Johnson)

From the cor. of secs. 1 and 12 only, on the E. bdy. of the Tp.

S. 88° 21' W., bet. secs. 1 and 12, marking and blazing the true line.

Descend 53 ft. along broken S. slope, along N. edge of logging.

4.11 Branch, 2 lks. wide, course S. 10° E.; asc. 21 ft. along broken S. slope.

8.03 Branch, 1 lk. wide, course S. 10° E.; desc. 5 ft. along broken S. slope.

20.91 Head of branch, 1 lk. wide, course S. 50° E.; asc. 116 ft. over broken S. slope.

28.92 Branch, 2 lks. wide, course S. 45° E.

34.39 Top of ascent; desc. 87 ft. over SW. slope.

40.62 The 1/4 sec. cor. of secs. 1 and 12, monumented with a basalt stone, 14 x 10 x 6 ins., firmly set, marked 1/4 on N. face, from which the original bearing trees:

A fir, 64 ins. diam., bears N. 71 1/2° W., 63 lks. dist., blaze healed. (Record: bears N. 69° W., 61 lks. dist.)

A madrone, 14 ins. diam., bears S. 16 1/4° W., 20 lks. dist., partial scribe marks visible. (Record: bears S. 15° W., 18 lks. dist.)

At the corner point

Set an iron post, 36 ins. long, 1 in. diam., 28 ins. in the ground, with brass cap mkd.

1/4  $\frac{S 1}{S 12}$   
1951

*FD OK  
By S. Ness  
10/95 M123-3 A.L.B*

from which

A fir, 36 ins. diam., bears S. 54 1/2° W., 134 lks. dist., mkd. 1/4 S12 BT.

Bury the original corner stone alongside the iron post.