

County Surveyor's Record, Douglas County, Oregon

Resurvey, Portion of Subdivisional Lines, T. 25 S., R. 2 W.

CHAINS	
72.65	Creek, 8 lks. wide, course N. 60° W.; asc. 275 ft. over general SW. slope.
83.00	Spur, slopes S. 80° W.; desc. 12 ft. over NW. slope.
83.84	The cor. of secs. 1, 2, 35, and 36, on the N. bdy. of the Tp., described in the field notes of the dependent resurvey of the S. bdy. of T. 24 S., R. 2 W., of this assignment. Land, mountainous. Soil, rocky clay lam. Timber, fir, hemlock, cedar, sugar pine, yew, madrone, chinquapin, and dogwood; undergrowth, vine maple, salal, huckleberry, Oregon grape, and rhododendron.
	From the cor. of secs. 1, 2, 11, and 12. N. 85° 42' W., bet. secs. 2 and 11. Ascend 49 ft. over SE. slope, along N. edge of logging.
2.42	Spur, slopes S. 45° W.; desc. 998 ft. over W. slope.
9.30	Enter bench, edge bears N. and SW.
23.20	Slope changes to NW. slope.
27.98	Branch, 1 lk. wide, course S. 85° W., thence along S. slope.
36.65	Slope changes to SW. slope.
39.58	The $\frac{1}{4}$ sec. cor. of secs. 2 and 11, monumented with a basalt stone, 14 x 8 x 6 ins., firmly set, marked $\frac{1}{4}$ on N. face, from which the original bearing trees: A fir, 42 ins. diam., bears N. 18° 45' E., 46 lks. dist., blaze healed. (Record bearing, N. 19° E.) A hemlock, 10 ins. diam., bears S. 40° W., 15 lks. dist., blaze healed. (Record bearing, S. 35 $\frac{1}{2}$ ° W.) At the corner point Set an iron post, 36 ins. long, 1 in. diam., 28 ins. in the ground, with brass cap mkd. $\frac{1}{4} \begin{array}{l} S 2 \\ S 11 \\ 1951 \end{array}$ No new accessories established. Bury the original corner stone alongside the iron post. N. 89° 04' W., beginning new measurement. Descend 74 ft. over SW. slope.
4.94	Rock Creek, 60 lks. wide, course S. 25° E.; asc. 81 ft. over S. slope.
11.91	Graded and graveled logging road, bears N. 10° W. and S. 5° E.