

County Surveyor's Record, Douglas County, Oregon

Resurvey, Portion of Subdivisional Lines, T. 25 S., R. 2 W.

CHAINS

N. 1° 52' E., bet. secs. 4 and 5.

Ascend 192 ft. over S. slope, through heavy timber and dense undergrowth.

- 4.77 Spur, slopes S. 30° W., asc. 19 ft. over W. slope.
- 8.40 Top of ascent; desc. 78 ft. over N. slope.
- 10.58 Branch, 2 lks. wide, course S. 80° W., asc. 204 ft. over SW. slope.
- 23.09 Branch, 3 lks. wide, course S. 45° W., asc. 336 ft. over S. slope.
- 27.45 Spur, slopes S. 70° W.; thence along W. slope.
- 34.90 Slope changes from W. to SW. slope.
- 36.86 Spur, slopes S. 50° W.; desc. 7 ft. over NW. slope.
- 39.04 Branch, 1 lk. wide, course N. 70° W.
- 39.14 The $\frac{1}{4}$ sec. cor. of secs. 4 and 5, monumented with a basalt stone, 18 x 8 x 6 ins., firmly set, marked $\frac{1}{4}$ on W. face, from which the original bearing trees:

A cedar, 40 ins. diam., bears N. 79° W., 42 lks. dist., blaze rotted and chopped open, scribe marks $\frac{1}{4}$ S5 visible. (Record: bears N. 77° W., 40 lks. dist.)

A hemlock, 16 ins. diam., bears S. 44° E., 3 lks. dist., blaze chopped partially open. (Record bearing, S. 51° E.)

At the corner point

Set an iron post, 36 ins. long, 1 in. diam., 28 ins. in the ground, with brass cap mkd.

$$\begin{array}{c} \frac{1}{4} \\ | \\ \text{S } 5 \text{ | S } 4 \\ | \\ 1951 \end{array}$$

from which

A hemlock, 8 ins. diam., bears N. 45° W., 57 lks. dist., mkd. $\frac{1}{4}$ S5 BT.

Bury the original corner stone alongside the iron post.

N. 6° 46' E., beginning new measurement.

Ascend 105 ft. over SW. slope.

- 7.90 Spur, slopes S. 65° W.; desc. 25 ft. over NW. slope.
- 12.10 Creek, 15 lks. wide, course S. 50° W.; asc. 350 ft. over steep S. slope, changing to broken SW. slope.
- 25.75 Spur, slopes S. 60° W.; desc. 25 ft. along W. slope.
- 28.16 Corner of Parcels 41 and 42, sec. 4, as shown in Court Decree "Civil No. 60-135, Oregon". The corner is monu-