

County Surveyor's Record, Douglas County, Oregon

Resurvey, Portion of Subdivisional Lines. T. 25 S., R. 2 W.

CHAINS

mented with an iron pipe, 24 ins. long $\frac{3}{4}$ in. diam., firmly driven 18 ins. in the ground, from which

A fir, 33 ins. diam., bears N. $45\frac{1}{2}^{\circ}$ E., 10 lks. dist., marked P41 S4 BT.

A fir, 70 ins. diam., bears S. $34\frac{3}{4}^{\circ}$ E., 98 lks. dist., marked P42 S4 BT.

Ascend 190 ft. over broken SW. slope.

45.96 The cor. of secs. 4, 5, 32, and 33, on the N. bdy. of the Tp., described in the field notes of the dependent resurvey of the S. bdy. of T. 24 S., R. 2 W., of this assignment.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, hemlock, sugar pine, cedar, maple, yew, madrone, dogwood, and chinquapin, undergrowth, vine maple, salal, huckleberry, Oregon grape, and rhododendron.

From the cor. of secs. 4, 5, 8, and 9.

N. $89^{\circ} 20'$ W. bet. secs. 5 and 8.

Descend 10 ft. along S. slope, through heavy timber and dense undergrowth.

4.99 Spur, slopes S. 50° W.; desc. 87 ft. over W. slope.

6.17 Branch, 3 lks. wide, course S.; asc. 116 ft. over SE. slope.

11.14 Spur, slopes S. 50° W.; desc. 167 ft. over W. slope.

14.90 Harrington Creek, 181 lks. wide, course S.; asc. 697 ft. over NE. slope.

40.52 The $\frac{1}{4}$ sec. cor. of secs. 5 and 8, monumented with a broken basalt stone, 14 x 8 x 8 ins., firmly set, marked $\frac{1}{4}$ on N. face, from which the original bearing trees:

A hemlock, 16 ins. diam., bears N. $13^{\circ} 45'$ E., 29 lks. dist., scribe marks $\frac{1}{4}$ S5 BT visible. (Record: bears N. 14° E., 27 lks. dist.)

A yew, 24 ins. diam., bears S. 41° E., 37 lks. dist., blaze rotted, partial scribe marks visible. (Record: bears S. 40° E., 36 lks. dist.)

At the corner point

Set an iron post, 36 ins. long, 1 in. diam., 28 ins. in the ground, with brass cap mkd.

$$\frac{1}{4} \frac{S \ 5}{S \ 8}$$

1951

from which

A hemlock, 14 ins. diam., bears S. 52° E., 62 lks. dist., mkd. $\frac{1}{4}$ S8 BT.