

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of S. Bdy., T. 25 S., R. 5 W.

## CHAINS

Surveyor, in 1955:

A fir, 18 ins. diam., bears N.  $20^{\circ}$  E., 224 lks. dist., mkd. with a healed blaze, facing the corner.

A fork of a fir, 25 ins. diam., bears S.  $85^{\circ}$  E., 910 lks. dist., mkd. with a healed blaze, facing the corner.

At the corner point

Set an iron post, 28 ins. long  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap marked *9/86*

T 25 S  
R 6 W | R 5 W

S 36 | S 31

S 1 | S 6

T 26 S

1963

FD OK PER M102-48  
BY BENTZ

No suitable trees available in secs. 1 and 36 within limits.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, oak, madrone, cedar, and alder; undergrowth, young timber, hazel, arrowwood, Oregon grape, salal, vines, ferns, and grass.

Dependent Resurvey of a Portion of Subdivisional Lines,  
T. 25 S., R. 5 W., Willamette Meridian, Oregon

(Restoring the 1871 survey by William H. Byars)

From the cor. of secs. 1, 2, 35, and 36, on the S. bdy. of the Tp., remonumented by James Byron, Deputy County Surveyor, in 1960, with an iron post, 36 ins. long, 1 in. diam., protruding 18 ins. above ground, firmly set, with brass cap marked

T 25 S R 5 W

S 35 | S 36

S 2 | S 1

T 26 S R 5 W

1960

from which the remaining original bearing trees:

A madrone snag, 12 ins. diam., bears N.  $7\frac{1}{2}^{\circ}$  E., 96 lks. dist., mkd. with a rotted blaze.

A fir, 47 ins. diam., bears S.  $42\frac{1}{2}^{\circ}$  E., 7 lks. dist., mkd. with illegible scribing on an opened blaze.

A madrone snag, 22 ins. diam., bears N.  $40\frac{1}{2}^{\circ}$  W., 88 lks. dist., mkd. with a rotted blaze.

and bearing trees marked by Byron:

A fir, 17 ins. diam., bears N.  $51^{\circ}$  E., 19 lks. dist., mkd. with a pitched-over blaze.

A fir, 10 ins. diam., bears S.  $20^{\circ}$  W., 89 lks. dist., mkd. with a pitched-over blaze.