

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 25 S., R. 5 W.

CHAINS

A maple, 10 ins. diam., bears N. 37° W., 16 lks. dist., mkd. T25S R5W S35 CS BT, on open blaze.

N. 0° 14' E., bet. secs. 35 and 36.

Ascend 145 ft. over broken SE. slope, through scattering timber and light undergrowth.

13.25 Creek, 1 lk. wide, course S. 85° E.; asc. 90 ft. over SW. slope.

17.40 Spur, slopes SE.; asc. 75 ft. over SE. slope.

23.55 Draw, drains SE.; asc. 105 ft. over S. slope.

29.00 Ridge, bears N. 80° E. and S. 70° W.; desc. 170 ft. over N. slope.

35.85 Creek, 4 lks. wide, course N. 80° W.; asc. 105 ft. over S. slope.

39.52 Point for the $\frac{1}{4}$ sec. cor. of secs. 35 and 36, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap marked

$$\begin{array}{c} \frac{1}{4} \\ \text{S } 35 \text{ | } \text{S } 36 \\ \text{T } 25 \text{ S | R } 5 \text{ W} \\ 1963 \end{array}$$

from which

A white oak, 11 ins. diam., bears N. 62° E., 13 lks. dist., mkd. $\frac{1}{4}$ S36 BT.

A black oak, 12 ins. diam., bears N. 72° W., 32 lks. dist., mkd. $\frac{1}{4}$ S35 BT.

Ascend 270 ft. over broken SW. slope.

40.50 Enter open prairie, edge bears E. and SW.

52.00 Spur ridge, bears N. 80° W. and S. 80° E.; desc. 250 ft. over N. slope.

53.35 Fence, bears N. 80° W. and S. 80° E.; enter scattering timber and medium undergrowth, edge bears E. and W.

59.28 Point for the N $1/16$ sec. cor. of secs. 35 and 36.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap marked

$$\begin{array}{c} \text{N } 1/16 \\ \text{S } 35 \text{ | } \text{S } 36 \\ \text{T } 25 \text{ S | R } 5 \text{ W} \\ 1963 \end{array}$$

from which

A fir, 9 ins. diam., bears S. 74° E., 78 lks. dist., mkd. N $1/16$ S36 BT.

A fir, 9 ins. diam., bears N. $7\frac{1}{2}^{\circ}$ W., 41 lks. dist., mkd. N $1/16$ S35 BT.