

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 26 S., R. 3 W.

CHAINS

- 40.31 Top of ascent, slopes W.; desc. 16 ft. over NW. slope.
- 40.94 Point for the $\frac{1}{4}$ sec. cor. of secs. 14 and 15, at proportionate distance; there is no remaining evidence of the original corner.
- Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap marked
- T 26 S R 3 W
S 15 | S 14
1962
- from which
- A cedar, 25 ins. diam., bears N. $20\frac{1}{2}^{\circ}$ E., 60 lks. dist., mkd. $\frac{1}{4}$ S14 BT.
- A cedar, 20 ins. diam., bears N. 75° W., 29 lks. dist., mkd. $\frac{1}{4}$ S15 BT.
- Descend 95 ft. over broken NW. slope.
- 45.75 Creek, 1 lk. wide, course N. 80° W.; desc. 22 ft. over broken NW. slope.
- 47.82 Crrek, 1 lk. wide, course W.; desc. 24 ft. over broken NW. slope.
- 49.75 S. edge of marshy area, 20 lks. wide, drains NW.; asc. 4 ft. over broken SW. slope.
- 51.68 Top of ascent, slopes W.; desc. 40 ft. over NW. slope, changing to W. slope.
- 59.15 Crreek, 3 lks. wide, course S. 80° W.; asc. 36 ft. over SW. slope.
- 61.41 Point for the N $\frac{1}{16}$ sec. cor. of secs. 14 and 15.
- Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap marked
- N $\frac{1}{16}$
S 15 | S 14
1962
- from which
- A fir, 17 ins. diam., bears N. 77° E., 62 lks. dist., mkd. N $\frac{1}{16}$ S14 BT.
- A cedar, 26 ins. diam., bears N. $75\frac{1}{2}^{\circ}$ W., 43 lks. dist., mkd. N $\frac{1}{16}$ S15 BT.
- Ascend 83 ft. over SW. slope.
- 68.54 Leave timber, edge bears E. and W.; enter open burned and logged area.
- 69.94 Spur slopes SW.; desc. 17 ft. over NW. slope.
- 72.82 Ravine drains S. 60° W.; asc. 35 ft. over SW. slope.
- 75.93 Spur, slopes W.; desc. 79 ft. over NW. slope.
- 79.63 Ravine, drains NW.; asc. 8 ft. over SW. slope.