

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines. T. 26 S., R. 3 W.

CHAINS

40.25

Point for the  $\frac{1}{4}$  sec. cor. of secs. 21 and 22, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 26 ins. in the ground, with brass cap marked

T 26 S R 3 W

$\frac{1}{4}$

S 21 | S 22

1962

from which

A fir, 20 ins. diam., bears S.  $72\frac{1}{2}^{\circ}$  E., 32 lks. dist., mkd.  $\frac{1}{4}$  S22 BT.

A fir, 16 ins. diam., bears S.  $25^{\circ}$  W., 159 lks. dist., mkd.  $\frac{1}{4}$  S21 BT.

Descend 283 ft. over NE. slope.

58.33

Draw, drains E.; desc. 391 ft. over NE. slope.

80.50

Point for the cor. of secs. 15, 16, 21, and 22, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 26 ins. in the ground, with brass cap marked

T 26 S R 3 W

S 16 | S 15

S 21 | S 22

1962

from which

A cedar, 12 ins. diam., bears N.  $46^{\circ}$  E., 90 lks. dist., mkd. T26S R3W S15 BT.

A hemlock, 27 ins. diam., bears S.  $34^{\circ}$  E., 97 lks. dist., mkd. T26S R3W S22 BT.

A hemlock, 6 ins. diam., bears S.  $32^{\circ}$  W., 34 lks. dist., mkd. T26S R3W S21 BT.

A cedar, 13 ins. diam., bears N.  $11^{\circ}$  W., 62 lks. dist., mkd. T26S R3W S16 BT.

The corner falls in boulder-filled draw, drains E.

Land, hilly.

Soil, clay loam and humus.

Timber, fir, cedar, hemlock, pine, madrone, maple, tanoak, and chinquapin; undergrowth, hazel, fern,

Oregon grape, fir reproduction, poison oak, arrowwood, thimbleberry, and salal.

From the cor. of secs. 14, 15, 22, and 23.

N.  $89^{\circ}$  16' W., bet. secs. 15 and 22.

Descend 126 ft. over NW. slope, through heavy timber and dense undergrowth.

4.00

Britt Creek, 5 lks. wide, course N.; asc. 244 ft. over E. slope.