

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 26 S., R. 3 W.

## CHAINS

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 28 ins. in the ground, with brass cap marked

T 26 S R 3 W

$\frac{1}{4}$  S 10

S 15

1962

Reset the local iron pipe inside the iron post.

S.  $89^{\circ}$  33' W., beginning new measurement.

Ascend 63 ft. over E. slope, through heavy timber and moderate undergrowth.

- 3.39 Top of ascent, slopes N.; asc. 21 ft. along gentle N. slope changing to NE. slope.
- 15.11 Spur, slopes NE.; continue along N. slope.
- 19.05 Creek, 3 lks. wide, course NE.; asc. 22 ft. over NE. slope.
- 19.83 Point for the W  $1/16$  sec. cor. of secs. 10 and 15.  
Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap marked
- W  $1/16$   $\frac{S}{S}$   $\frac{10}{15}$   
1962
- from which
- A cedar, 14 ins. diam., bears N.  $62^{\circ}$  E., 3 lks. dist., mkd. W  $1/16$  S10 BT.
- A fir, 27 ins. diam., bears S.  $34^{\circ}$  E., 89 lks. dist., mkd. W  $1/16$  S15 BT.
- Ascend 141 ft. over NE. slope, changing to E. slope.
- 30.94 Enter meadow, edge bears NW. and SE.
- 35.28 Leave meadow, edge bears N. and S.; enter heavy timber and moderate undergrowth.
- 39.66 The cor. of secs. 9, 10, 15, and 16.  
Land, hilly.  
Soil, rocky clay loam.  
Timber, fir, cedar, pine, hemlock, yew, maple, madrone, chinquapin, alder, and dogwood; undergrowth, hazel, fern, poison oak, Oregon grape, huckleberry, arrowwood, and grass.
- 
- From the corner of secs. 21, 22, 27, and 28.  
N.  $89^{\circ}$  28' W., bet. secs. 21 and 28.  
Ascend 30 ft. over E. slope, through heavy timber and light undergrowth.
- 1.40 Woven and barbed wire fence bears N. and S.
- 3.20 Dirt road, 10 lks. wide, bears N.  $40^{\circ}$  W. and S.  $40^{\circ}$  E.