

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 1, T. 26 S., R. 3 W.

CHAINS

	Ascend 81 ft. over SE. slope, through open logged area.
1.70	Dirt road, 15 lks. wide, bears N. and S.
7.15	Ridge, bears N. 20° E. and S. 20° W., desc. 236 ft. over NW. slope, through heavy timber and moderate undergrowth.
19.73	The SE 1/16 sec. cor. of sec. 1. Descend 459 ft. over NW. slope.
31.43	Three-wire transmission line, bears N. 50° W. and S. 15° E.
36.99	Dirt road, 15 lks. wide, bears N. 15° E. and S. 15° W.
38.74	Dirt road, 15 lks. wide, bears N. 10° W. and S. 10° E.
39.46	The center S 1/16 sec. cor. of sec. 1.
<hr/>	
	From the center S 1/16 sec. cor. of sec. 1. N. 87° 17' W., on the E. and W. center line of the SW ¹ / ₄ of sec. 1. Descend 65 ft. over W. slope, through heavy timber and moderate undergrowth.
3.05	Dirt road, 15 lks. wide, bears N. 20° W. and S. 20° E.
5.90	North Umpqua Highway, bituminous pavement, 32 lks. wide, bears NW. and SE.
9.05	Rock Creek, 120 lks. wide, course S.; asc. 21 ft. over E. slope.
11.54	Dirt road, 15 lks. wide, bears N. 70° W. and S. 70° E.
17.60	Top of ascent, slopes S.; desc. 37 ft. over SW. slope.
23.48	Right bank of North Umpqua River, course W. from SE.; enter river.
34.81	Right bank of North Umpqua River, course SW. from E.; asc. 18 ft. along river bottom.
40.01	The S 1/16 sec. cor. of secs. 1 and 2.
<hr/>	
	From the center N 1/16 sec. cor. of sec. 1. N. 88° 30' W., on the E. and W. center line of the NW ¹ / ₄ of sec. 1. Ascend 70 ft. over SE. slope, through moderate undergrowth, along the N. edge of logged area.
14.65	Creek, 3 lks. wide, course SE.; asc. 255 ft. over broken E. slope.
19.96	Corner of barbed wire fence, extending S. and W.
27.75	Top of knoll; desc. 27 ft. over W. slope.
31.13	Bottom of descent, slopes S.; asc. 46 ft. over E. slope.
36.04	Spur, slopes SE.; desc. 33 ft. over SW. slope.