

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 30 S., R. 2 W.

CHAINS	above ground, firmly set, with brass cap marked County Surveyor's Office WIT. COR. $\frac{1}{4}$ S23 S24 to 100' SOUTH 1959, from which trees marked by Byron:
	<p>A yellow pine, 17 ins. diam., bears N. $59\frac{3}{4}^{\circ}$ E., 71 lks. dist., mkd. with a healed blaze.</p> <p>An oak, 10 ins. diam., (identical tree marked by Irving, in 1940) bears S. $54\frac{1}{2}^{\circ}$ W., 43 lks. dist., mkd. WC on an open blaze on the NE. side of the tree.</p> <p>Ascend 30 ft. over general S. slope, through scattering timber and moderate undergrowth.</p>
51.70	Enter an open field, edge bears E. and W.
54.62	From this point the SE. cor. of a frame house, bears West, 30 lks. dist. House is 30 x 42 ft., long side bears E. and W.
	Continue through yard and garden.
56.15	Power line, bears N. 65° E. and S. 65° W.
57.15	Graveled road, 15 lks. wide, bears N. 80° W. and S. 80° E.
58.45	Wire fence, bears E. and W.; leave yard and garden.
58.85	Paved highway, 30 lks. wide, bears N. 85° E. and W., in slight curve; asc. 80 ft. over steep S. slope, through heavy timber and dense undergrowth.
60.90	Dirt road, 15 lks. wide, bears E., and S. 70° W., 40 lks. to road intersection from which dirt roads bear N. and S. 60° W.
61.02	Point for the N $1/16$ sec. cor. of secs. 23 and 24.
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap marked
	N $1/16$ S 23 S 24 T 30 S R 2 W 1963
	from which
	A fir, 15 ins. diam., bears S. $72\frac{1}{4}^{\circ}$ E., 88 lks. dist., mkd. N $1/16$ S24 BT.
	A fir, 38 ins. diam., bears N. 32° W., 130 lks. dist., mkd. N $1/16$ S23 BT.
	Continue over nearly level land, drains W.
61.34	Wire fence, bears E., and W. 14 lks. to fence corner, thence N.; enter open field; continue along fence.
65.00	Enter dense timber and undergrowth; edge bears NE. and SW.
71.60	Dry wash, 25 lks. wide, drains S. 75° W.; asc. 60 ft. over SE. slope.