

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 22 S., R. 4 W.

CHAINS

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap marked

S 1/16  
S 20 | S 21  
T 22 S R 4 W  
1963

from which

A fir, 11 ins. diam., bears N. 46° E., 5 lks. dist., mkd. S 1/16 S21 BT.

A fir, 13 ins. diam., bears N. 72° W., 31½ lks. dist., mkd. S 1/16 S20 BT.

Ascend 70 ft. over S. slope.

23.20 Spur, slopes SW.; desc. 90 ft. over broken W. slope.

32.90 Wet draw, drains W., desc. 10 ft. over N. slope.

40.02 The ¼ sec. cor. of secs. 20 and 21, perpetuated and recorded by Milo E. Godfrey, Deputy County Surveyor, monumented with an iron post, 1 in. diam., firmly set, protruding 14 ins. above ground, with brass cap marked

COUNTY SURVEYOR'S OFFICE

T 22 S R 4 W  
¼ S 20 | S 21  
1961

*FD OK  
3/93 M116-66  
NESS*

from which the remains of the original bearing trees:

A stump hole with maple shoots, bears N. 62° E., 34 lks. dist.

A fir snag, 48 ins. diam., bears S. 50° W., 23 lks. dist., no marks remaining.

bearing trees mkd. by Godfrey:

A broken cedar stump, 17 ins. diam., bears N. 22° E., 16 lks. dist., mkd. with a healed blaze.

A cedar, 9 ins. diam., bears N. 56¼° W., 32½ lks. dist., mkd. ¼ S20 CS BT on partially healed double blaze.

and new bearing trees:

A cedar, 10 ins. diam., bears S. 88° E., 53 lks. dist., mkd. ¼ S21 BT.

A cedar, 9 ins. diam., bears S. 27° W., 44 lks. dist., mkd. ¼ S20 BT.

N. 0° 11' W., beginning new measurement.

Descend 15 ft. over W. slope.

1.60 Creek, 1 lk. wide, course S. 60° W.; asc. 325 ft. over SE. slope, changing to SW. slope.

9.60 Dirt road, 50 lks. wide, bears E. and W.

19.975 Point for the N 1/16 sec. cor. of secs. 20 and 21.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap marked