

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 22 S., R. 4 W.

CHAINS

Land, mountainous.  
Soil, rocky clay.  
Timber, fir, cedar, madrone, maple, dogwood, and alder;  
undergrowth, young fir, hazel, arrowwood, live oak,  
manzanita, huckleberry, salal, Oregon grape, black-  
berry, thimbleberry, and vines.

From the cor. of secs. 8, 9, 16, and 17, perpetuated by  
Wilford N. Haines, Registered Land Surveyor No. 239,  
with a 1 in. T-iron, firmly set, protruding 8 ins.  
above ground, with aluminum cap marked Wilford N.  
Haines, No. 239, Drain, Oregon, at record bearing and  
distance from the original SW. bearing tree:

A cedar snag, 35 ins. diam., bears S. 20° W.,  
10 lks. dist., mkd. 22 S on open blaze.

and trees mkd. by the Douglas County Surveyor:

A maple, 30 ins. diam., bears N. 57½° E., 110 lks.  
dist., mkd. with a healed blaze.

A maple, 38 ins. diam., bears S. 70° E., 108 lks.  
dist., mkd. with a healed blaze.

A cedar snag, 14 ins. diam., bears N. 60° W.,  
47 lks. dist., mkd. T22S R4W S8 BT.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins.  
in the ground, with brass cap marked

T 22 S R 4 W
S 8   S 9
S 17   S 16
1963

*FD. OK 9/12  
D. Peck  
M15-77*

from which new bearing trees:

A cedar, 22 ins. diam., bears S. 4° W., 155 lks.  
dist., mkd. T22S R4W S17 BT.

A cedar, 7 ins. diam., bears N. 35½° W., 53 lks.  
dist., mkd. T22S R4W S8 BT.

Reset the T-iron alongside the iron post.

N. 0° 10' E., bet. secs. 8 and 9.

Ascend 30 ft. over SW. slope, along woven wire fence,  
through old logged area.

2.90

Wet draw, drains S. 45° E.; asc. 260 ft. over broken  
SE. slope.

19.955

Point for the S 1/16 sec. cor. of secs. 8 and 9.

Set an iron post, 28 ins. long, 2½ ins. diam., 23 ins.  
in the ground, with brass cap marked

S 1/16
S 8   S 9
T 22 S R 4 W
1963

from which

A hemlock, 14 ins. diam., bears S. 55° E., 61 lks.  
dist., mkd. S 1/16 S9 BT.