

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 22 S., R. 4 W.

CHAINS

A fir, 23 ins. diam., bears S. $29\frac{1}{2}^{\circ}$ W., 60 lks. dist., mkd. S 1/16 S8 BT.

Ascend 140 ft. over SE. slope.

- 23.25 Enter meadow, edge bears N. 80° E. and S. 80° W.
- 25.00 Telephone lines, 2 wire, bears N. 80° E. and S. 80° W.
- 25.15 Power line, 2 wires, bears N. 65° E. and S. 65° W.
- 26.00 Dirt road, 25 lks. wide, bears E. and W.
- 34.40 High tension power line, 3 cables, bears N. 45° E. and S. 45° W.
- 34.90 Dirt road, 25 lks. wide, bears NE. and SW.
- 37.50 Enter timber, edge bears NE. and SW.
- 39.50 Dirt road, 20 lks. wide, bears NE. and SW.
- 39.80 Ridge, bears NE. and SW.; continue along top of ridge.
- 39.91 The $\frac{1}{4}$ sec. cor. of secs. 8 and 9, perpetuated and recorded by Deputy County Surveyor, James W. Byron, in 1958, monumented with an iron post, 1 in. diam., firmly set, protruding 8 ins. above ground, with brass cap marked

COUNTY SURVEYOR'S OFFICE

T 22 S
 $\frac{1}{4}$ S 8 | S 9
 R 4 W
 1958

*FOOK 9/92
 D. Peck
 MHS-77*

from which the remains of an original bearing tree,

A rotted oak stump, 10 ins. diam., bears N. 40° W. 56 lks. dist., no marks remaining.

and bearing trees mkd. by the County Surveyor:

A fir, 27 ins. diam., bears N. $77\frac{1}{2}^{\circ}$ E., 99 lks. dist., mkd. with a healed double blaze.

A fir, 23 ins. diam., bears N. 20° W., 46 lks. dist., mkd. with a healed double blaze.

N. $0^{\circ} 07'$ E., beginning new measurement.

Descend 15 ft. along broken W. slope, through heavy timber and medium undergrowth.

- 0.30 Woven wire fence, bears NE. and SW.
- 7.00 Spur, slopes N. 75° W.; desc. 35 ft. along broken W. slope.
- 11.00 Spur, slopes N. 50° W.; desc. 115 ft. over NE. slope.
- 14.30 Draw, drains N. 55° W.; desc. 20 ft. over broken W. slope.
- 17.20 Creek, 1 lk. wide, course W.; asc. 20 ft. over SW. slope.
- 19.79 Point for the N 1/16 sec. cor. of secs. 8 and 9.