

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 22 S., R. 4 W.

CHAINS

Land, mountainous.  
Soil, rocky clay.  
Timber, fir, hemlock, cedar, oak, madrone, maple, dogwood, and alder; undergrowth, hazel, arrowwood, huckleberry, salal, Oregon grape, vine maple, ferns and vines.

From the cor. of secs. 3, 4, 9, and 10, previously described.

N. 89° 36' W., bet. secs. 4 and 9.

Descend 95 ft. over S. slope, changing to SW. slope, along S. edge of logged area.

14.90 Ridge, bears NE. and W.; desc. 100 ft. along top of ridge.

20.80 Leave ridge, bears E. and S. 65° W.; desc. 55 ft. over NW. slope.

29.10 Bottom of descent slopes N.; asc. 70 ft. over E. slope.

41.11 The  $\frac{1}{4}$  sec. cor. of secs. 4 and 9, perpetuated and recorded by Deputy County Surveyor, James W. Byron, in 1958, when remains of the other bearing tree were existent, monumented with an iron post, 1 in. diam., firmly set protruding 12 ins. above ground, with brass cap marked

## COUNTY SURVEYOR'S OFFICE

T 22 S

$$\frac{\frac{1}{4} \text{ S } 4}{\text{S } 9}$$

R 4 W

1958

from which the remaining original bearing tree,

A cedar, 35 ins. diam., bears N. 14 $\frac{1}{4}$ ° E., 15 lks. dist., mkd.  $\frac{1}{4}$  S on opened blaze and re-marked  $\frac{1}{4}$  S4 CS BT by Byron. (Record bearing, N. 13° E., 15.10 lks. dist.)

and a bearing tree mkd. by Byron,

A hemlock, 7 ins. diam., bears S. 29 $\frac{1}{2}$ ° W., 33 lks. dist., mkd. with a healed double blaze.

S. 89° 23' W., beginning new measurement.

Ascend 10 ft. over E. slope.

2.35 Ridge, bears N. 10° E. and S. 10° W.; desc. 260 ft. over NW. slope.

6.05 Dirt road, 25 lks. wide, bears N. 15° E. and S. 15° W.

6.50 Enter old logged area, edge bears E. and SW.

11.15 High tension power line, 3 cables, bears N. 30° E. and S. 30° W.

14.80 Draw, drains N. 15° W.; asc. 55 ft. over NE. slope.