

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 22 S., R. 6 W.

CHAINS

No other suitable bearing trees available within limits.

Reset water pipe alongside the iron post.

Land, mountainous.

Soil, rocky clay and loam.

Timber, fir, cedar, hemlock, maple, madrone, oak, dogwood, chinquapin, willow and alder; undergrowth, young timber, hazel, arrowwood, salal, huckleberry, poison oak, Oregon grape, vine maple, blackberry, vines and ferns.

From the cor. of secs. 22, 23, 26 and 27.

N. 88° 21' W., bet. secs. 22 and 27.

Descend 230 ft. over W. slope; along S. edge of old logged area, through moderate undergrowth.

14.75 Creek, 1 lk. wide, course S. 20° W.; asc. 95 ft. over SE. slope.

17.65 Enter logged area, edge bears NE. and SW.

19.75 Spur, slopes S. 25° W.; desc. 165 ft. over W. slope.

23.80 Dirt road, 25 lks. wide, bears N. and S.

33.50 Creek, 1 lk. wide, course S.; asc. 70 ft. over E. slope.

34.50 Thence along N. edge of timber, edge bears S. and W.

37.00 Spur, slopes S.; desc. 20 ft. along broken S. slope.

40.97 Point for the $\frac{1}{4}$ sec. cor. of secs. 22 and 27, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap marked

$$\frac{1}{4} \begin{array}{l} S 22 \\ S 27 \end{array}$$

T 22 S R 6 W
1963

from which

A fir, 13 ins. diam., bears N. 65° W., 104 lks. dist., mkd. $\frac{1}{4}$ S22 BT.

A fir, 10 ins. diam., bears S. 42° W., 47 $\frac{1}{2}$ lks. dist., mkd. $\frac{1}{4}$ S27 BT.

Ascend 10 ft. over E. slope.

43.90 Spur, slopes S.; desc. 75 ft. over W. slope.

48.75 Draw, drains S.; asc. 90 ft. over E. slope.

53.40 Spur, slopes S.; desc. 55 ft. over W. slope.

55.45 Draw, drains S.; asc. 95 ft. over E. slope.

59.70 Spur, slopes S.; asc. 35 ft. along S. slope.

71.75 Enter logged area, edge bears E. and S.