

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 22 S., R. 6 W.

CHAINS

from which a new bearing tree

A fir, 5 ins. diam., bears S. $48\frac{1}{4}^{\circ}$ W., $19\frac{1}{2}$ lks. dist., mkd. T22S R6W S21 BT.

Deposit mkd. stone alongside the iron post.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, hemlock, dogwood, ash, alder, yew, maple, willow, madrone and chinquapin; undergrowth, young timber, hazel, arrowwood, manzanita, huckleberry, salal, poison oak, Oregon grape, vine maple, ferns and vines.

From the cor. of secs. 14, 15, 22, and 23.

S. $89^{\circ} 56'$ W., bet. secs. 15 and 22.

Ascend 95 ft. over SE. slope, changing to E., through moderate timber and dense undergrowth.

5.15 Spur, slopes N.; desc. 170 ft. over W. slope.

8.90 Creek, 2 lks. wide, course N.; asc. 690 ft. over E. slope.

26.35 Spur, slopes N.; desc. 285 ft. over W. slope, changing to NW. slope.

36.35 Spur, slopes N. 50° W.; desc. 160 ft. over W. slope.

40.42 Point for the $\frac{1}{4}$ sec. cor. of secs. 15 and 22, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 23 ins. in the ground, with brass cap marked

$$\frac{1}{4} \frac{S 15}{S 22}$$

T 22 S R 6 W
1963

from which

A fir, 23 ins. diam., bears N. $7\frac{1}{2}^{\circ}$ E., 70 lks. dist., mkd. $\frac{1}{4}$ S15 BT.

A fir, 9 ins. diam., bears S. $32\frac{1}{2}^{\circ}$ W., $26\frac{1}{2}$ lks. dist., mkd. $\frac{1}{4}$ S22 BT.

Descend 285 ft. over W. slope.

46.95 Draw, drains N. 50° W.; desc. 130 ft. over W. slope.

51.10 Dirt road, 25 lks. wide, bears N. and S.

52.65 Creek, 4 lks. wide, course N.; asc. 160 ft. over NE. slope.

59.85 Enter old logged area, edge bears NW. and SE.

60.63 Point for the W $1/16$ sec. cor. of secs. 15 and 22.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap marked