

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 24 S., R. 4 W.

CHAINS	
	<p>from which</p> <p>A cedar, 20 ins. diam., bears N. 73° E., 58 lks. dist., mkd. S 1/16 S25 BT.</p> <p>A fir, 7 ins. diam., bears S. 4$\frac{3}{4}$° W., 297 lks. dist., mkd. S 1/16 S26 BT.</p> <p>Ascend 230 ft. over broken SW. slope.</p>
20.60	Woven wire fence, bears E. and W.; enter heavy timber and dense undergrowth.
26.00	Spur, slopes S. 40° W.; desc. 220 ft. over broken NW. slope.
39.98	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 25 and 26, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 28 ins. long, 2$\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center;"> $\begin{array}{c} \frac{1}{4} \\ \text{S } 26 \text{ S } 25 \\ \text{T } 24 \text{ S } \text{ R } 4 \text{ W} \\ 1963 \end{array}$ </div> <p>from which</p> <p>A hemlock, 12 ins. diam., bears N. 50° E., 71 lks. dist., mkd. $\frac{1}{4}$ S25 BT.</p> <p>A fir, 12 ins. diam., bears S. 21$\frac{1}{2}$° W., 62 lks. dist., mkd. $\frac{1}{4}$ S26 BT.</p> <p>Ascend 5 ft. over SW. slope, along east edge of old logging area.</p>
41.10	A spur, slopes W.; desc. 110 ft. over NW. slope.
46.80	Creek, 2 lks. wide, course S. 40° W.; asc. 270 ft. over broken SE. slope.
56.80	Ridge, bears N. 75° E. and S. 75° W.; desc. 240 ft. over general NW slope, along a wire fence.
70.30	Draw, drains W.; asc. 165 ft. over SW. slope, entering oak timber.
79.96	<p>The cor. of secs. 23, 24, 25, and 26, determined at the intersection of woven wire fences, which bear N., S. and W.; from which the remaining original bearing tree,</p> <p>A rotted fir stump, 30 ins. diam., bears S. 6$\frac{1}{2}$° W., 1,220 lks. dist., mkd. with portions of a rotted blaze. (Record distance, 1216 lks.)</p> <p>and bearing trees not of record:</p> <p>A white oak, 7 ins. diam., bears S. 34$\frac{1}{2}$° E., 23 lks. dist., mkd. with a rotted blaze and partial scribe mks.</p> <p>A white oak, 10 ins. diam., bears S. 45° W., 28 lks. dist., with a healed blaze facing the corner.</p> <p>A white oak, 11 ins. diam., bears N. 36$\frac{3}{4}$° W., 57 lks. dist., mkd. S23 on an open blaze.</p>