

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 25, T. 24 S., R. 4 W.

CHAINS	
0.75	Ascend 15 ft. over SW. slope, through scattering timber and undergrowth. Barbed wire fence, bears E. and W. 40 lks. to fence corner, from which fences extend E. and S.
1.50	Top of ascent, slopes W.; desc. 60 ft. over NW. slope.
17.75	Cantell Creek, 2 lks. wide, course S. 20° W.; asc. 20 ft. over S. slope.
19.77	Point for the center S 1/16 sec. cor. of sec. 25. Set an iron post, 28 ins. long, 2½ ins. diam., 23 ins. in the ground, with brass cap mkd.
	$\begin{array}{c} C \\ \\ S\ 1/16\ \ S\ 25 \\ \\ C \\ 1963 \end{array}$
	from which
	A fir, 21 ins. diam., bears N. 42½° E., 54 lks. dist., mkd. CS 1/16 S25 BT.
	A fir, 17 ins. diam., bears S. 82¾° W., 12 lks. dist., mkd. CS 1/16 S25 BT.
	Ascend 525 ft. over broken S. slope.
39.54	Point for the center ¼ sec. cor. of sec. 25, at intersection with E. and W. center line. Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
	$\begin{array}{c} C\ \frac{1}{4}\ S\ 25 \\ 1963 \end{array}$
	from which
	A fir, 32 ins. diam., bears N. 41¼° W., 48 lks. dist., mkd. C¼ S25 BT.
	A fir, 12 ins. diam., bears S. 7° E., 104 lks. dist., mkd. C¼ S25 BT.
	Ascend 80 ft. over broken S. slope, through heavy timber and dense undergrowth.
41.65	Spur, slopes S. 15° E.; asc. 420 ft. over SE. slope.
52.70	Ridge, bears N. 40° E. and S. 40° W. about one chain west of top of E. butte; desc. 815 ft. over NE. slope.
77.70	Creek, 1 lk. wide, course N. 35° E.; asc. 5 ft. over SE. slope.
79.21	The ¼ sec. cor. of secs. 24 and 25. From the ¼ sec. cor. of sec. 25, only, on the E. bdy. of the Tp., monumented with an iron post, 1 in. diam., set, mkd. and witnessed as described in the official record. S. 89° 53' W., on the E. and W. center line of sec. 25. Descend 25 ft. over SW. slope, through heavy timber and dense undergrowth.