

County Surveyor's Record, Douglas County, Oregon

Remonumentation, Original Corners, T. 24 S., R. 4 W.

CHAINS

Oak stump hole, bears N. 89° W., 100 lks. dist.
(Record bearing, N. 88° W.)

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 24	S R 4 W
S 15	S 14
S 22	S 23
1963	

from which new bearing trees:

A fir, 14 ins. diam., bears N. 74° E., 88 lks. dist., mkd. T24S R4W S14 BT.

An oak, 12 ins. diam., bears S. $86\frac{1}{2}^{\circ}$ E., 116 lks. dist., mkd. T24S R4W S23 BT.

A cedar, 24 ins. diam., bears N. 41° W., 654 lks. dist., mkd. T24S R4W S15 BT.

There is no bearing tree available within limits in sec. 22.

From this point the SE. cor. of Claim No. 46, bears S. 88° W., 4.50 chs. dist., mkd. by a corner of fences extending N. and W. (Record bearing, N. $89^{\circ} 30'$ W., 4.53 chs. dist.)

From the same point the $\frac{1}{4}$ sec. cor. of secs. 14 and 15 is located 39.98 chs. northerly, exact bearing not determined, recently remonumented by the County Surveyor, by reference to evidence of the original survey, with an iron post, $1\frac{1}{2}$ ins. diam., 8 ins. above ground, firmly set, with 3 in. brass cap mkd. T24S R4W $\frac{1}{4}$ S14 S15 1963.

The $\frac{1}{4}$ sec. cor. of secs. 15 and 16, determined at record distance from each of the original bearing trees:

An oak, dead and down, 30 ins. diam., bears N. 46° E., 80 lks. dist., mkd. with old axe marks on rotted blaze. (Record bearing, N. 56° E.)

An oak, 27 ins. diam., bears N. 41° W., 53 lks. dist., with blaze healed. (Record bearing, N. 37° W.)

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 21 ins. in the ground, with brass cap mkd.

	$\frac{1}{4}$
S 16	S 15
T 24	S R 4 W
1963	

from which new bearing trees:

A fir, 15 ins. diam., bears S. 26° E., 26 lks. dist., mkd. $\frac{1}{4}$ S15 BT.