

County Surveyor's Record, Douglas County, Oregon

Remonumentation, Original Corners, T. 24 S., R. 4 W.

CHAINS

A fir, 14 ins. diam., bears S. $78\frac{1}{2}^{\circ}$ W., 15 lks. dist., mkd. $\frac{1}{4}$ S16 BT.

The $\frac{1}{4}$ sec. cor. of secs. 5 and 6, determined at record bearing and distance from the remains of the original bearing trees:

An oak snag, 30 ins. diam., bears S. 65° E., 37 lks. dist., mkd. with a burned blaze.

An oak stump hole, bears S. 67° W., 10 lks. dist.

At the corner point set an iron post, 20 ins. long, $2\frac{1}{2}$ ins. diam., 21 ins. in the ground, with brass cap mkd.

$$\begin{array}{c} \frac{1}{4} \\ S\ 6\ | \ S\ 5 \\ T\ 24\ S\ | \ R\ 4\ W \\ 1963 \end{array}$$

from which new bearing trees:

A fir, 8 ins. diam., bears East, 80 lks. dist., mkd. $\frac{1}{4}$ S5 BT.

A fir, 12 ins. diam., bears S. 32° W., 196 lks. dist., mkd. $\frac{1}{4}$ S6 BT.

(Remonumenting a corner established by Hathorn in 1856)

The NE. cor. of Claim No. 46, in Sec. 15, determined at record bearing and distance from the remains of the original NE. bearing tree.

A sawed madrone stump, 34 ins. diam., bears N. 70° E., 23 lks. dist., with rotted double blaze and partial scribe marks visible in reverse on remains of tree lying downhill to the SE.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

$$\begin{array}{c} T\ 24\ S\ R\ 4\ W \\ S\ 15 \end{array}$$

$$\begin{array}{|l} \hline D.L.C. \\ No. 46 \\ \hline 1963 \end{array}$$

from which new bearing trees:

A fir, 8 ins. diam., bears S. 27° E., 81 lks. dist., mkd. T24S R4W S15 BT.

A sawed fir stump, 22 ins. diam., bears S. 72° W., 25 lks. dist., mkd. DLC No. 46.