

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 24 S., R. 7 W.

CHAINS

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

N 1/16
S 6 | S 5
T 24 S R 7 W
1963

from which

A fir, 10 ins. diam., bears S. 51° E., 62 lks. dist., mkd. N 1/16 S5 BT.

A fir, 11 ins. diam., bears S. 47° W., 75 lks. dist., mkd. N 1/16 S6 BT.

Ascend 70 ft. over S. slope.

29.70 Spur, slopes W.; desc. 90 ft. over N. slope.

36.38 Intersect the S. bdy. of T. 23 S., R. 7 W., at the original closing corner of secs. 5 and 6, previously described.

From this point the cor. of secs. 31 and 32 only, on S. bdy. of T. 23 S., R. 7 W., bears N. $89^{\circ} 43'$ E., 2.31 chs. dist., previously described.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, hemlock, maple, yew, madrone, alder, and chinquapin; undergrowth, salal, hazel, arrowwood, huckleberry, poison oak, vine maple, vines and ferns.

Subdivision of Sec. 5, T. 24 S., R. 7 W.,
Willamette Meridian, Oregon

The following subdivision of section 5 was executed in conformity with legal surveying practice. The record of true line notes only, is set forth in the following field notes.

From the $\frac{1}{4}$ sec. cor. of secs. 5 and 8.

N. $0^{\circ} 12'$ E., on the N. and S. center line of sec. 5.

Ascend 5 ft. over S. slope, through heavy timber and moderate undergrowth.

0.40 Dirt road, 20 lks. wide, bears N. 30° E. and S. 30° W.

1.10 Creek, 2 lks. wide, course E.; asc. 110 ft. over S. slope.

11.30 Top of ascent, slopes E.; desc. 25 ft. along broken E. slope.

35.40 Bottom of descent, slopes E.; asc. 35 ft. over SE. slope.

37.00 Spur, slopes NE.; desc. 30 ft. over NW. slope.

40.18 Point for the center $\frac{1}{4}$ sec. cor. of sec. 5, at intersection with the E. and W. center line.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins.